

# MFORTDELGRO ENGINEERING PTE LTD

## PAIR ESTIMATE\*

VEHICLE NO SHC1373G  
MAKE HYUNDAI  
MODEL IONIQ

DATE: 23.06.23  
MVA JUMANI  
DOA: 23.06.23

## INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			Ry \$459.40
10	REAR BUMPER CLIPS			net \$22.00
1	REAR BUMPER CENTRE MOULDING			Cur \$451.25
1	REAR BUMPER BEAM			R \$394.80
1	REAR FOG LAMP			x \$201.50
1	ANTENNA SMARTKEY			R \$40.50
	<b>SUB TOTAL</b>		473.25	<b>\$1,569.45</b>
	<b>LESS 25%</b>	20%	378.60	\$313.89
	<b>DISCOUNTED TOTAL</b>			<b>\$1,255.56</b>
	REAR NUMBER PLATE			Cur \$55.00
	REVERSE SENSOR			un R \$180.00
	REAR BUMPER MAT			un \$50.00
	<b>SUB TOTAL</b>		55	<b>\$285.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING		630	350 \$400.00
	SPRAY PAINT			250 \$300.00
	REMOVE/REFIX REVERSE SENOR			30 \$50.00
	<b>TOTAL LABOUR</b>		1063.60	
	<b>ESTIMATE TOTAL</b>		154850	<b>\$750.00</b>
			2 days	<b>\$2,290.86</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjun 9745744  
WP 73/2/73 CYM  
02 days  
Tanjun e Chhandu in  
L/S Resurvey after repair

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: