

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: **22.06.2023**

GBC4616H

INSURANCE: **INCOME (L.S.)**MODEL: **Hyundai Ioniq**MVA: **LIM T S**VEHICLE NO.: **SH 8873C**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Front Bumper	1		\$ 481.10	48
	Front Bumper Upper Moulding	1		\$ 368.50	368.50
	Front Bumper Clips	10	\$ 2.20	\$ 22.00	22.00
	Front Bumper Side Brkt LH	1		\$ 35.00	35.00
	Front Wheel Rim LH	1		\$ 1,124.20	1,124.20
	Front Fender LH	1		\$ 588.80	588.80
	Front Fender (Blue-Drive) LH	1		\$ 26.60	26.60
	Front Fender Shield LH	1		\$ 164.70	164.70
	HeadLamp LH	1		\$ 2,110.30	2,110.30
	DayLight LH	1		\$ 642.50	642.50
	DayLight Grille LH	1		\$ 93.45	93.45
	Bonnet	1		\$ 2,253.80	2,253.80
	Wing Mirror Garnish LH	1		\$ 64.10	64.10
			5950.20		
			4760.16		
	SUB TOTAL			\$ 7,975.05	
	LESS 20%			\$ 1,595.01	
	TOTAL SPARE PARTS			\$ 6,380.04	
	Front Fender Adv.Sticker LH			\$ 100.00	NETT
	Labour Charge				
	Panel Beating			\$ 800.00	825
	Spray Painting			\$ 900.00	750
	Check Wirings			\$ 40.00	30
	Tuff Kote			\$ 60.00	30
	Wheel Alignment			\$ 120.00	120.00
			1335		
	TOTAL LABOUR		6195.16	\$ 1,920.00	
	ESTIMATE TOTAL		LS 44950 3 days	\$ 8,400.04	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Signature: C. Mahandian
Date: 22/6/23