



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED #42-0116 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT23001903	Page	1
Registration No	: SMC8760S	Date	: 24. Jun 2023		
Chassis No	: JHMRU1830GX204016	Customer No.	: WZF002		
Model	: HRV LX-SIN CVT YM 2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: CHONG KIM HWA	Engine No	: L15B4534021		
Ins Policy No.	:	Date Time	: 24. Jun 2023 10:35:35 AM		
Date of Accident	: 22/6/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHONG KIM HWA OWNER INSURER: FWD ACC DATE: 22/06/2023 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SG5075P						
60260-T7A-J00ZZ	PANEL COMPL.FR.FENDER	1	422.70	25	317.02	25.36	342.38
74157-T7A-J01ZC	PROTECTOR,L.FR.WHEEL ARCH	1	164.40	25	123.30	9.86	133.16
74150-T7A-N00	FENDER ASSYL.FR.INNER	1	99.10	25	74.32	5.95	80.27
91501-TR0-003	CLIP,INNER FENDER	11	2.80	25	23.10	1.85	24.95
04711-T7A-N00ZZ	FACE,FR.BUMPER	1	524.30	25	393.22	31.46	424.68
04712-T7A-900ZZ	FACE,FR.BUMPER LOWER	1	255.30	25	191.47	15.32	206.79
71190-T7A-000	BEAML.FR.BUMPER UPPER	1	28.40	25	21.30	1.70	23.00
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE	1	11.80	25	8.85	0.71	9.56
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE	1	11.80	25	8.85	0.71	9.56
91505-TM8-003	CLIP,BUMPER	22	2.30	25	37.95	3.04	40.99
33100-T7S-E11	HEADLIGHT ASSY,R.	1	1974.40	25	1480.80	118.46	1599.26
33150-T7S-E11	HEAD LIGHT ASSY,L.	1	1974.40	25	1480.80	118.46	1599.26
60400-T7A-901ZZ	BULKHEAD COMP,FR.	1	465.00	25	348.75	27.90	376.65
42700-T7A-J92	DISK,ALUMINIUM WHEEL	1	836.20	25	627.15	50.17	677.32
44306-T7A-N00	DRIVESHAFT ASSYL.	1	1150.90	25	863.17	69.05	932.22
01463-T2G-A01	CALIPER SET,FR.	1	46.80	25	35.10	2.81	37.91
44300-T6A-J51	BEARING ASSYFR.HUB	1	147.90	25	110.92	8.87	119.79
44600-T0B-A00	HUB ASSYFR.	1	200.40	25	150.30	12.02	162.32
45251-TA0-A02	DISKFR.BRAKE	1	212.20	25	159.15	12.73	171.88

Printed on 24/6/2023 1:18:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED #42-0116 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT23001903	Page	2
Registration No	: SMC8760S	Date	: 24. Jun 2023	Customer No.	: WZF002
Chassis No	: JHMRU1830GX204016	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15B4534021
Model	: HRV LX-SIN CVT YM 2016	Date Time	: 24. Jun 2023 10:35:35 AM	Surveyor Name	:
Owner's Name	: CHONG KIM HWA	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 22/6/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
45255-T7A-000	GUARDFR.BRAKE SPLASH	1	29.90	25	22.42	1.79	24.21
45022-T4N-H02	PAD SET,FR.	1	242.00	25	181.50	14.52	196.02
51216-T7A-000	KNUCKLEL.FR.	1	260.70	25	195.52	15.64	211.16
51220-STK-A01	JOINTFR.LOWER BALL	1	107.80	25	80.85	6.47	87.32
51306-T7A-004	BUSHR.FR.STABILIZER HOLDER	1	8.30	25	6.22	0.50	6.72
51325-T7A-003	LINK COMPL.FR.STABILIZER	1	51.20	25	38.40	3.07	41.47
51360-T7J-H11	ARM ASSYL.FR.LOWER	1	262.50	25	196.87	15.75	212.62
57455-T7A-003	SENSOR ASSYL FR	1	40.40	25	30.30	2.42	32.72
51621-T7M-H02	ABSORBER UNITL.FR.SHOCK	1	324.70	25	243.52	19.48	263.00
51401-T7A-J12	SPRINGFR.	1	99.10	25	74.32	5.95	80.27
51722-T7A-013	RUBBERFR.BUMP STOPPER	1	23.90	25	17.92	1.43	19.35
51694-TX6-A01	RUBBERL.FR.SPRING LOWER	1	15.50	25	11.62	0.93	12.55
50200-T7A-023	SUB FRAME COMPFR.SUSPENSION	1	807.90	25	605.92	48.47	654.39
50275-T5E-000	STAYR.RR.SUB FRAME	1	12.70	25	9.52	0.76	10.28
50276-T5E-000	STAYL.RR.SUB FRAME	1	15.50	25	11.62	0.93	12.55
53211-T7A-N01	COLUMN COMPSTEERING	1	2441.50	25	1831.12	146.49	1977.61
53213-T7A-N01	SHAFT COMPSTRG INTER MEDIATE	1	249.00	25	186.75	14.94	201.69
53320-T5A-000	COVERSTEERING JOINT	1	3.80	25	2.85	0.23	3.08
77901-T5A-J80	SUB CORDCABLE REEL	1	55.70	25	41.77	3.34	45.11
35000-T0A-003	SENSOR ASSYSTREERING	1	244.40	25	183.30	14.66	197.96
77900-T5A-J22	REEL ASSY,CABLE	1	292.60	25	219.45	17.56	237.01
77960-T7S-Z81	SRS UNIT	1	806.70	25	605.02	48.40	653.42
77970-T6A-J11	SENSOR ASSYSIDE IMPACT	2	140.90	25	211.35	16.91	228.26
Sum Item					11463.65	917.07	12,380.72

BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00		280.00	22.40	302.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	580.00		580.00	46.40	626.40
BMS00R	RENEW ECU & ERASE ENGINE WARNING LIGHT	1	650.00		650.00	52.00	702.00

Printed on 24/6/2023 1:18:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED #42-0116 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT23001903	Page	3
Registration No	: SMC8760S	Date	: 24. Jun 2023		
Chassis No	: JHMRU1830GX204016	Customer No.	: WZF002		
Model	: HRV LX-SIN CVT YM 2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: CHONG KIM HWA	Engine No	: L15B4534021		
Ins Policy No.	:	Date Time	: 24. Jun 2023 10:35:35 AM		
Date of Accident	: 22/6/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BPBODY	TOWING ACC SCENE AUTHORISE WORKSHOP FOR REPORTING	1	120.00		120.00	9.60	129.60
BPBODY	TOWING FROM AUTHORISE WORKSHOP TO KAH MOTOR	1	120.00		120.00	9.60	129.60
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS. (N)	1	1625.00		1625.00	130.00	1755.00
BPBODY	REPLACE STEERING COLUMN ASSY	1	1300.00		1300.00	104.00	1404.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	3250.00		3250.00	260.00	3510.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	4160.00		4160.00	332.80	4492.80
Sum Labor					12185.00	974.80	13,159.80

Survey By	_____						
Date & Time	_____						
Excess	_____						
Status	_____						
Signature	_____						
					Total Amount	23,648.65	1,891.87
					Total (Inclusive of GST)		25,540.52

Printed on 24/6/2023 1:18:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.