

2ND AUTO PTE LTD

15 Kaki Bukit Road 4 #01-53 Bartley Bizcentre Singapore 417808

Main Line : (65) 6741 6741 Fax : 6746 7939

*not allowed
her
26/6/23
d/s # 3300 /
2 days*

23-Jun-23

Vehicle Reg No. : SBR 58 R
Model : LEXUS ES300H

Estimated repair cost for the vehicle as mentioned above

Qty	Description		Amt S(\$)
<u>List Items</u>			
1	Front headlamp -RH	CNa	3702.20 \$ 5,178.50 ✓
1	Front grille	11	\$ 1,118.90 X
1	Front grille chrome moulding	Scn	\$ 353.50 ✓
1	Front grille logo	Scn	108.20 \$ 459.90 ✓
1	Front bumper	2	\$ 1,235.70 X
1	Front bumper inner sponge	11	\$ 127.50 X
1	Front bumper reinforcement	11	\$ 455.80 X
2	Front bumper side retainers	11	\$ 110.20 X
1	Front fender -RH	11	\$ 1,270.00 X
			\$ 10,310.00
		Less 10%	\$ 1,031.00
			\$ 9,279.00
<u>Special Nett Items</u>			
1	Front bumper clip (1 set)	11	\$ 60.00 X
1	Front number plate	11	\$ 100.00 X
			\$ 160.00
<u>LABOUR CHARGES</u>			
1	To check wiring and reset headlamps focusing.		\$ 80.00 20
2	To remove and refit front sensor.	11	\$ 150.00 X
3	To apply undercoating.	11	\$ 100.00 X
4	Panel beating.		\$ 1,400.00 200
5	To re-spray painting on the affected areas.		\$ 1,200.00 200
			\$ 2,930.00

Grand Total :

\$ 12,369.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*2-416290
102
3747.51
420
4167.51*