



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD		Ref: CS3/HSB23006404/Anp3	
10 MARINA BOULEVARD		Date: 26/06/2023	
#48-01 MARINA BAY FINANCIAL CENTRE TOWER			
2SINGAPORE 018983		Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHC 3802Y	Veh. Inspected	SNF 2662D
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04NIF	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	26/06/2023
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/06/2023	Inspection Date	26/06/2023
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			