

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLE4384Y
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000
 ATTN: Motor Claim Department
 WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 22/06/2023
 TP Veh Reg No: SLE1552Z

NOT Authorised
1/1/2023
FAX: 64153727
Mercury After Repair
12 days

Estimate No: ES2300656/YISHUN
 Date: 26 Jun 2023
 Policy No: 5129024465
 Veh Reg No: SLE4384Y
 Make/Model: HONDA VEZEL 1.5 CVT
 Chassis No: RU11114739
 Engine No: L15B4034750
 Reg. Date: 21/07/2016

Estimate Repair Cost to Vehicle No :SLE4384Y

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	553.10	1 PC	R ₁ 553.10	✓
2 REAR BUMPER LH SIDE PAD	172.80	1 PC	R ₂ 172.80	✓
3 REAR BUMPER LH REFLECTOR	145.80	1 PC	C ₁ 145.80	✓
4 REAR BUMPER RH REFLECTOR	145.80	1 PC	R ₂ 145.80	X
5 REAR BUMPER CLIP	3.80	6 PC	R ₂ 22.80	✓
6 REAR LH WHEEL ARC GARNISH	129.90	1 PC	R ₂ 129.90	✓
7 REAR TAILGATE	1,072.80	1 PC	R ₂ 1,072.80	✓
8 TAILGATE EMBLEM 'VEZEL'	50.00	1 PC	R ₂ 50.00	✓
9 TAILGATE INNER LOCK	98.50	1 PC	R ₂ 98.50	✓
10 TAILGATE INNER RUBBER	95.00	1 PC	R ₂ 95.00	50% ✓
11 TAILGATE INNER TRIM BOARD	185.00	1 PC	R ₂ 185.00	?
12 TAILGATE REFLECTOR	287.60	2 PC	R ₂ 575.20	L ✓
13 TAILGATE OUTER GARNISH	267.60	1 PC	R ₂ 267.60	?
14 TAILGATE LOGO	24.70	1 PC	R ₂ 24.70	?
15 REAR WINDSCREEN GLASS MOULDING	131.80	1 PC	R ₂ 131.80	✓
16 LH TAILLAMP	509.60	1 PC	R ₂ 509.60	✓
17 REAR END PANEL	454.10	1 PC	R ₂ 454.10	✓
18 REAR END PANEL INNER TOP GARNISH	57.90	1 PC	R ₂ 57.90	✓
19 REAR TOOL BOX	156.00	1 PC	C ₁ 156.00	✓
20 REAR SMART KEY SENSOR	58.00	1 PC	R ₂ 58.00	?
21 REAR SPARE TYRE COMPARTMENT	838.60	1 PC	R ₂ 838.60	✓
22 REAR SPARE TYRE COMPARTMENT UNDER COVER	223.10	1 PC	R ₂ 223.10	?
23 FRONT BUMPER	884.10	1 PC	R ₂ 884.10	?
24 FRONT BUMPER REINFORCEMENT	266.10	1 PC	R ₂ 266.10	?
25 FRONT BUMPER CLIP	3.80	6 PC	R ₂ 22.80	?
26 FRONT GRILLE BASE	312.30	1 PC	C ₁ 312.30	✓
			7,453.40	
		Less 20%	1,490.68	5,962.72
Special Net				
27 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	R ₂ 40.00	✓
28 REAR NUMBER PLATE	35.00	1 PC	R ₂ 35.00	✓
29 REVERSE SENSOR	200.00	1 SET	Shan 200.00	✓
			275.00	275.00
Labour				
30 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 22/06/2023

TP Veh Reg No: SLE1552Z

Estimate No: ES2300656/YISHUN

Date: 26 Jun 2023

Policy No: 5129024465

Veh Reg No: SLE4384Y

Make/Model: HONDA VEZEL 1.5 CVT

Chassis No: RU11114739

Engine No: L15B4034750

Reg. Date: 21/07/2016

Estimate Repair Cost to Vehicle No :SLE4384Y

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
31 REMOVE & REFIX REAR BUMPER, TAILLAMPS, TAILGATE, LOCK ASSY, TOP SPOILER, REAR WIPER, TO CUTTING, WELDING & RENEW REAR END PANEL, REAR COMPARTMENT PANEL, TO STRAIGHTEN, KNOCKING & REPAIR REAR BOTH CHASSIS, REAR BOTH FENDERS & REALIGN THE SAME	1,300.00	1 LA	1,300.00	1200
32 REMOVE & REFIX SEAT, CARPET, GARNISH ETC	120.00	1 PC	120.00	✓
33 PUTTY & RESPRAY ON REAR COMPARTMENT, REAR BOTH FENDERS, REAR CHASSIS, REAR END PANEL, TAILGATE, REAR BUMPER	1,200.00	1 LA	1,200.00	900
34 REMOVE & REFIX FRT BUMPER, GRILLE, REINFORCEMENT & REALIGN THE SAME	300.00	1 LA	300.00	220
35 PUTTY & RESPRAY ON REAR BUMPER, REAR REINFORCEMENT	400.00	1 LA	400.00	200
36 RUSTPROOFING	60.00	1 LA	60.00	✓
37 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
			3,550.00	3,550.00
			Total	S\$ 9,787.72
			Add GST @ 8%	783.02
			Total Amount Payable	S\$ 10,570.74

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: