

SMC 47475

SMB 52845

SMRT Address
60 Woodland
FAX Number
Estimator Tel
Accident Rep
Date Generated
User ID

Section A - Accident Details

Registration Number	SHF105E
Case Reference Number	TAX/06/23/2063
Registration Date	26/12/19
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN SAY BONG
Type of Accident	Head To Side
Accident Date and Time	24/6/23 2:50 PM
Accident Reported Date and Time	26/6/23 8:19 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118738
Special Instruction to ARC, if any	TP/ TOWED
Prepared Date and Time	26/6/23 8:39 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$2,392.00	\$0.00
Total Spare Part Cost	\$6,907.89	\$0.00
Total Other Cost	\$1,959.76	\$0.00
TOTAL COST	\$12,273.65	\$0.00
Lump Sum Total	\$12,250.00	\$0.00
Number of Repair Days	8.0	5 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	26/06/2023 9:08 AM	
Signature		x Kenneth
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Auton
80 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera
User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicabl
TO REPAIR RH PORTION	\$1,014.00 <i>40d</i>	
Total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO RESPRAY FRONT FENDER RH	\$378.00 <i>20d</i>	
TO RESPRAY FRONT DOOR RH	\$378.00 <i>20d</i>	
TO RESPRAY ROCKER PANEL MOULDING	\$220.00 <i>X</i>	
TO RESPRAY RH REAR DOOR	\$378.00 <i>X</i>	
TO RESPRAY REAR FENDER RH	\$378.00 <i>X</i>	
TO RESPRAY RIM	\$220.00 <i>X</i>	
RESPRAY WHEEL CAP	\$220.00 <i>X</i>	
TO RESPRAY FRONT PILLAR RH	\$220.00 <i>X</i>	
Total Spray Painting & Panel Beating	\$2,392.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TOWING CHARGE	\$56.00 <i>✓</i>	
TO WASH AND VACUUM	\$60.00 <i>X</i>	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>20d</i>	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00 <i>30d</i>	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 <i>60d</i>	
TO REMOVE AND REFIT TYRE	\$120.00 <i>X</i>	
TO TRANSFER DOOR MECHANISM	\$240.00 <i>60d</i>	
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$593.76 <i>na ✓</i>	
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00 <i>?</i>	
TO REPLACE SUNDRY PARTS	\$100.00 <i>X</i>	
Total Other Costs	\$1,959.76	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace <i>na</i>	<i>✓</i>
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	25.00	\$1,055.85	Replace <i>na</i>	<i>X</i>
		48510-80A79	ABSORBER SET, SHOCK, FRONT RH	1.00	\$511.40	25.00	\$383.55	Replace	<i>?</i>
		45046-49255	END SET, TIE ROD, RH	1.00	\$202.30	25.00	\$151.73	Replace	<i>?</i>
		48068-47060	LOWER ARM SUB-ASSY, FRONT RH	1.00	\$823.20	25.00	\$617.40	Replace	<i>?</i>
		43211-47040	KNUCKLE, STEERING, RH	1.00	\$717.50	25.00	\$538.13	Replace	<i>?</i>
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace <i>na</i>	<i>X</i>
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace <i>na</i>	<i>X</i>
		53851-47061	PAD, FR WHEEL RH	1.00	\$65.00	25.00	\$48.75	Replace <i>na</i>	<i>✓</i>
		53827-47050	PROTECTOR, FR FENDER RH	1.00	\$101.80	25.00	\$76.35	Replace	<i>?</i>
		53857-12010	RETAINER, FR WHEEL RH	1.00	\$3.50	25.00	\$2.63	Replace	<i>X</i>
		53875-47120	LINER, FR FENDER, RH	1.00	\$219.10	25.00	\$164.33	Replace <i>na</i>	<i>✓</i>
		53801-47080	FENDER SUB-ASSY, FR , RH	1.00	\$1,060.70	25.00	\$795.53	Replace <i>na</i>	<i>✓</i>

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera
User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace <i>RC</i>	✓
		61013-47011	PILLAR, FRONT BODY, RH	1.00	\$378.90	25.00	\$284.17	Replace	X
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace <i>RC</i>	✓
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	7
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	✓
		68610-47040	CHECK ASSY, FRONT DOOR	1.00	\$199.40	25.00	\$149.55	Replace <i>RC</i>	X
		67861-47060	WEATHERSTRIP, FRONT DOOR RH	1.00	\$250.70	25.00	\$188.02	Replace <i>RC</i>	X
		68710-12151	HINGE UPPER RHF, DOOR	1.00	\$105.50	25.00	\$79.13	Replace <i>RC</i>	X
		68730-12120	HINGE LOWER RHF, DOOR	1.00	\$120.00	25.00	\$90.00	Replace <i>RC</i>	X
		67003-47211	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace <i>RC</i>	X
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace <i>RC</i>	X
Total					\$12,393.94		\$9,342.19		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ch
Total									

Not Author

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ^{or} after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: