

LKK Auto Consultants Pte Ltd (Co,Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 28 Jun 2023

Preliminary Advice

Vehicle No	: SKS2684H	Accident Date	: 22/06/2023
Make	: MERCEDES-BENZ B180	Policy No.	: DMPCSNW00039092307
Assignment Date	: 26/06/2023	Excess	: S\$0.00
Date of Inspection	: 27/6/2023	Est. Duration of Repair	: 11
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,326.46
Revised Amount	:S\$	12,246.46
Check Items (Estimated)	:S\$	5,040.00
Total	:S\$	17,286.46
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	20,587.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,413.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Lump sum repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .