Mennery (UKK) (1 Pmg & After Paint 2 days

Our Ref: SNB9695J Your Ref: YP4250M

S/NO	QTY	DESCRIPTIONS PARTS REPLACEMENT - LIST ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP		
					0-1	
1	1	REAR BUMPER		\$	Brilin 1,895.90	
2	1	REAR BUMPER INNER BRACKET RH		\$	125.90	
3	1	REAR BUMPER INNER BRACKET LH		\$	125.90	
4	1	REAR BUMPER LOWER GARNISH		\$	415.90	
5	1	REAR BUMPER SPONGE		\$	285.90	
6	1	REAR BUMPER REINFORCEMENT		\$	785.90	
		,	SUB TOTAL	\$	3,635.40	
		, *	LESS 10%	\$	363.54	
			TOTAL AMOUNT	\$	3,271.80	

Our Ref: SNB9695J Your Ref: YP4250M

S/NO	QTY	SPECIAL NETT ITEMS REAR BUMPER CLIPS	ASSESSED	EST. BY WORKSHOP		
1	1		CONDITION	\$	Ma 30.00	
	C4 54 55	9	SUB TOTAL	\$	30.00	
1 1 1 1			TOTAL PARTS COST	\$	3,301.86	

Our Ref: SNB9695J Your Ref: YP4250M

S/NO	DESCRIPTION LABOUR & PAINTWORK TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS			EST. BY WORKSHOP		
1				600.00	200	
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED			600.00	220	
3	TO REMOVE & REFIT REVERSE SENSORS		\$,	80.08	50	
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS			مم _{60.00}	X	
5	TO VACUUM, WAXING & CLEAN			en 50.00	X	
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)			₹ 50.00	X	
		TOTAL BEFORE GST	\$	4,741.86	1	
		GST 8%	\$	379.35	1	
		TOTAL (PARTS & LABOUR):	\$	5,121.21	1	

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage

found on the vehicle and have listed the breakdown of our finding and recommendation

Our Workshop has agreed to undertake the job at a sum of \$5,121.21 for lump sum with the later Repairer of the following: party insurance.

Yours Faithfully,

Ck Loh

Claims Estimator

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: