

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SCV20R
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000
 ATTN: Motor Claim Department
 WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 25/06/2023
 TP Veh Reg No: SNA6074B

FAX: 64153727

Not Authorize
Accord By Agent
21 days

Estimate No: ES2300672/YISHUN
 Date: 03 Jul 2023
 Policy No: 5123051502-01
 Veh Reg No: SCV20R
 Make/Model: NISSAN NOTE E-POWER
 Chassis No: JN1FAAE13Z0900312
 Engine No: HR12295776K
 Reg. Date: 27/06/2021

Estimate Repair Cost to Vehicle No :SCV20R

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
Net Price			SS	SS
1 REAR BUMPER	579.90	1 PC	579.90	✓
2 REAR BUMPER RH REFLECTOR	68.90	1 PC	68.90	✓
3 REAR BUMPER SPONGE	108.00	1 PC	108.00	✓
4 REAR BUMPER RH BRACKET	39.80	1 PC	39.80	✓
5 REAR BUMPER RH SIDE PAD	508.30	1 PC	508.30	✓
6 REAR BUMPER CLIP	4.50	6 PC	27.00	✓
7 REAR TAILGATE	1,352.80	1 PC	1,352.80	✓
8 TAILGATE INNER LOCK	142.80	1 PC	142.80	✓
9 TAILGATE INNER RUBBER	106.30	1 PC	106.30	✓
10 TAILGATE INNER TRIM BOARD	331.60	1 PC	331.60	✓
11 REAR TAILGATE DAMPERS	232.80	2 PC	465.60	✓
12 TAILGATE EMBLEM 'NOTE'	88.80	1 PC	88.80	✓
13 TAILGATE EMBLEM 'E-POWER'	56.40	1 PC	56.40	✓
14 REAR TAILGATE OUTER CENTRE GARNISH	416.00	1 PC	416.00	✓
15 TAILGATE REFLECTOR	273.40	2 PC	546.80	✓
16 TAILLAMP	347.90	2 PC	695.80	✓
17 REAR WINDSCREEN GLASS	1,333.30	1 PC	1,333.30	✓
18 REAR RH REVERSE SENSOR	258.20	2 PC	516.40	✓
19 REAR END PANEL	689.40	1 PC	689.40	✓
20 REAR END PANEL INNER TOP GARNISH	78.70	1 PC	78.70	✓
21 REAR RH FENDER	1,109.40	1 PC	1,109.40	✓
22 REAR RH FENDER INNER GARNISH	441.20	1 PC	441.20	✓
23 REAR RH FENDER INNER SHIELD	144.80	1 PC	144.80	✓
24 REAR RH DOOR INNER LOCK	191.90	1 PC	191.90	✓
25 FUEL DOOR PANEL	89.90	1 PC	89.90	✓
26 REAR RH DOOR LOWER STEP GARNISH	90.50	1 PC	90.50	✓
27 REAR COMPARTMENT PANEL TOP BOARD	483.10	1 PC	483.10	✓
28 REAR COMPARTMENT PANEL	680.90	1 PC	680.90	✓
29 REAR RH CHASSIS	625.30	1 PC	625.30	✓
30 REAR RH WHEEL HOUSING INNER	760.50	1 PC	760.50	✓
31 REAR RH DOOR	1,128.50	1 PC	1,128.50	✓
32 REAR RH DOOR INNER RUBBER	106.30	1 PC	106.30	✓
33 REAR RH WHEEL BEARING	385.60	1 PC	385.60	✓
			14,390.50	
		Less 10%	1,439.05	12,951.45
Special Net				
34 REAR AXLE	1,132.10	1 PC	1,132.10	✓
35 REAR RH SHOCK ABSORBER	123.30	1 PC	123.30	✓
36 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
37 REAR NUMBER PLATE	55.00	1 PC	55.00	✓
38 IN HOUSE CCTV RECORDER	380.00	1 PC	380.00	✓

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 25/06/2023

TP Veh Reg No: SNA6074B

Estimate No: ES2300672/YISHUN
Date: 03 Jul 2023
Policy No: 5123051502-01
Veh Reg No: SCV20R
Make/Model: NISSAN NOTE E-POWER
Chassis No: JN1FAAE13Z0900312
Engine No: HR12295776K
Reg. Date: 27/06/2021

Estimate Repair Cost to Vehicle No :SCV20R

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
39 REAR RH TYRE	230.00	1 PC	230.00	50.00
40 REAR WINDSCREEN GLASS TINTED FILM	100.00	1 PC	100.00	2,060.40
Labour				
41 TOWING (BY KING DOLLY) - BILL ATTACHED	100.00	1 LA	100.00	7
42 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	120.00
43 REMOVE & REFIX REAR SEAT,CARPET,GARNISH, TOP ROOF LINING,SAFETY BELT AND WASH CUSHION	200.00	1 LA	200.00	120.00
44 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE,REAR WIPER,AUTO LOCKING,SPOILER,TO CUTTING,WELDING & RENEW REAR COMPARTMENT,REAR END PANEL,REAR RH FENDER,REAR RH DOOR,REAR RH CHASSIS,REAR RH WHEEL HOUSING (REFER BELOW)	3,500.00	1 LA	3,500.00	280.00
45 TO KNOCKING & REPAIR REAR LH FENDER, TOP ROOF PANEL,RH ROCKER PANEL & REALIGN CHASSIS	0.00	1 LA	0.00	
46 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN	250.00	1 LA	250.00	7
47 REMOVE & REFIX REAR RH DOOR GLASS	60.00	1 LA	60.00	x
48 PUTTY & REPSRAY ON REAR BUMPER,TAILGATE,TAILGATE OUTER GARNISH,REAR PANEL,REAR COMPARTMENT,REAR BOTH FENDERS, TOP ROOF PANEL,REAR RH CHASSIS,REAR RH DOOR,RH ROCKER PANEL,REAR RH FLOORBOARD PANEL	2,500.00	1 LA	2,500.00	200.00
49 REMOVE & REFIX REAR UNDERCARRIAGE,AXLE,WHEEL BEARING	280.00	1 LA	280.00	220.00
50 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
51 REMOVE & REFIX HYBRID BATTERY & RESET SYSTEM	200.00	1 LA	200.00	✓
52 RUSTPROOFING	200.00	1 LA	200.00	120.00
			7,470.00	7,470.00
			Total	S\$ 22,481.85
			Add GST @ 8%	1,798.55
			Total Amount Payable	S\$ 24,280.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE