

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0229/23

DATE : 24-JUN-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD #09-01

S(068897)

TEL : 63954779/67143369

FAX : 63953768

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR KIEW KUAY SEOW

ADDRESS : BLK 15 BEDOK RESERVOIR VIEW

#15-04

S(478933)

TELEPHONE NO : 91132958

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 2100450310-07

VEHICLE NO : SKZ5749Z

MODEL CODE : FRLARBZJ11UEA--A--

MODEL/YEAR : NISSAN QASHQAI 1.2

ENGINE NO : HRA2215275A

CHASSIS NO : SJNFEAJ11U1541347

MILEAGE : 188865 KM

DATE IN : 24/06/2023

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 23/06/2023

-9645 0084 elmer@fanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKZ5749Z

-----

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW FRT BUMPER REPAIR FRT RH FENDER	780.00	390
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	500.00	<del>250.50</del> 500 ✓
3	ZZ/003	SUPPLY FRT LICENSE PLATE		
		TOTAL LABOUR CHARGES	1280.00	

-----

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKZ5749Z

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
1	SUNDRIES <i>nu</i>	NPN			<i>20</i> <del>50.00</del>
2	FRT LICENCE PLATE <i>nu</i>	FLP			<i>+</i> 60.00
3	RH HEADLAMP <i>nu</i>	26010-4EA0A	748.70	<i>x</i>	
4	GRILLE-RADIATOR <i>nu</i>	62310-4EA1A	643.90	<i>x</i>	
5	RH STAY FRT BUMPER <i>?</i>	F2214-4EAMA	215.90	<i>?</i>	
6	UPPER REINFORCEMENT FRT BUMPER <i>?</i>	F2030-4ENMA	926.50	<i>?</i>	
7	UPPER ENERGY ABSORBER FRT BUMPER <i>?</i>	62090-4EA1B	268.40	<i>?</i>	
8	LOWER REINFORCEMENT FRT BUMPER <i>?</i>	62030-4EJ1A	463.20	<i>?</i>	
9	RH ENERGY ABSORBER FRT BUMPER <i>?</i>	62090-4EA0C	85.20	<i>?</i>	
10	RH FOGLAMP GARNISH <i>?</i>	62256-4EA0C	99.10	<i>?</i>	
11	FRT BUMPER <i>Delud</i>	62022-4EA0H	836.40	<i>✓</i>	
12	FRT RH SIDE BRACKET FRT BUMPER <i>nu</i>	62222-4EA0A	26.00	<i>+</i>	
SUB TOTAL			4313.30	0.00	110.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			862.66	0.00	0.00
GRAND TOTAL			3450.64	0.00	110.00
OVERALL TOTAL			3560.64		

LEGEND: REMARKS ( OK ) = APPROVED, REMARKS ( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKZ5749Z

-----  
TOTAL LABOUR CHARGES                    1280.00  
TOTAL SPARE PARTS CHARGES            3560.64  
-----  
GRAND TOTAL                                4840.64 \*  
-----

\* All charges do not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME                                        :  
SURVEYED DATE                            :  
AUTHORIZED DATE                        :  
EXCESS CLAUSE                            :            0.00  
LIABILITY                                   :            0.00  
REMARKS                                    :

Adrian Lij  
P/P 28/06/23  
04 Pags  
96893735.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: