



AP AUTOMOTIVE SERVICES PTE LTD
 ROC / GST REG NO : 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

Estimation

Date 27/6/2023
 Vehicle GBF 7847Y
 Make/Model TOYOTA DYNA 150
 Chassis No. JTFAT35Y60K207578

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	FRONT BUMPER	1	\$ 628.16	\$ 628.16
2	HEADLAMP LH	1	\$ 1,130.50	\$ 1,130.50
3	HEADLAMP RUBBER LH	1	\$ 59.50	\$ 59.50
4	FRONT CORNER PANEL LH	1	\$ 356.00	\$ 356.00
5	FRONT CENTRE PANEL	1	\$ 486.20	\$ 486.20
6	FRONT WINDSCREEN RUBBER	1	\$ 272.82	\$ 272.82
7	FRONT WINDSCREEN GLASS	1	\$ 108.75	\$ 108.75
8	FRONT SIDE MIRROR LH	1	\$ 566.93	\$ 566.93
9	FRONT STEP PANEL GARNISH LH	1	\$ 414.57	\$ 414.57
10	FRNT STEP PANEL (INNER) LH	1	\$ 108.75	\$ 108.75
11	FRONT DOOR LH	1	\$ 1,853.70	\$ 1,853.70
12	FRONT DOOR OUTER HANDLE LH	1	\$ 271.20	\$ 271.20
13	FRONT DOOR FRAME RUBBER LH	1	\$ 208.60	\$ 208.60
14	FRONT DOOR INNER RUBBER LH	1	\$ 189.55	\$ 189.55
15	FRONT DOOR OUTER MOULDING LH	1	\$ 186.10	\$ 186.10
16	FRONT DOOR HINGE LH	2	\$ 118.40	\$ 236.80
17	FRONT DOOR CHECKER LH	1	\$ 177.50	\$ 177.50
				\$ 7,255.63
			Less 25%	\$ 1,813.91
			Total	\$ 5,441.72

	S/Nett Items			
1	FRONT PANEL SEALANT	2	\$ 80.00	\$ 160.00
2	FRONT DOOR STICKER "ADDRESS" LH	1	\$ 280.00	\$ 280.00
3	FRONT NUMBER PLATE	1	\$ 80.00	\$ 80.00
4	FRONT WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
			Total	\$ 600.00

	LABOUR			
1	SPRAY PAINT ON AFFECTED AREAS	1	\$ 1,600.00	\$ 1,600.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00
3	TO CHECK WHEEL ALIGNMENT	1	\$ 350.00	\$ 350.00
4	TO TRANSFER FRONT DOOR LH MECHANISM	1	\$ 80.00	\$ 80.00
5	TO REFOCUS HEADLAMP BEAM	1	\$ 60.00	\$ 60.00
6	TO PERFORM RUST PROOFING	1	\$ 250.00	\$ 250.00

		Total	\$	3,740.00
		Parts Replacement Amount	\$	6,041.72
		Total Amount For Labour	\$	3,740.00
		Total Amount	\$	9,781.72

Taufik 97495749 / 62563561

28/6/23 @ 150pm

LIS Resurvey after repair
 Taufik @ Kuantan
 03 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: