



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|---|--|--------------------|
| LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428 | | | Ref: CS3/LIP22012501/Kny3m4-1 Date: 10/07/2023 Code: LIP | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SMM 3573X | Veh. Inspected | SNA 1722Y |
| | Policy No. | C0133845 | Coverage (\$) | 0.00 |
| | Claim No. | AVS22/3467 | Excess (\$) | 0.00 |
| | Assign From | ANDY SEAH | Assign Date | 26/06/2023 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | VOLKSWAGEN TOURAN (A) | c.c | 1598 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | WVGZZZ1TZFW020573 | Colour | WHITE |
| | Odometer | 206426 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 225/45 R17 | BRIDGESTONE | 2 mm |
| | L/H Front Tyre | 225/45 R17 | BRIDGESTONE | 2 mm |
| | R/H Rear Tyre | 225/45 R17 | FALKEN | 5 mm |
| | L/H Rear Tyre | 225/45 R17 | FALKEN | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 08/12/2022 | Inspection Date | 14/12/2022 |
| | Survey held at | KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722 | | |
| 5a. Remarks | | | | |
| | A)REGISTRATION DATE: 14 JAN 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | |