

ASS. REC. BY: Taufikh

REF: B/CT/23006478/T9P3

ASSIGNMENT

2025 Dec

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: Q27K.
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seac _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMH 12566 Yr Regn: 2011, Jan.
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda City c.c. 1497
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 179899 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MRHGM26709-P02 0534
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/55R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. _____		D.O.I. <u>28/6/23</u>
Survey held at <u>Yew Tee Auto Make-Build</u>		
Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or <u>Frt. o/s</u>		
The U/G / Chassis frame / Body Structure affected due to collision.		

Date / Time	Action / Instruction
	Taufikh finalised LS \$1800, 3 days. (Red \$2804, 61%)

Date/Time, File Pass to? ☐ : Prel. Report
1) 25/07 Typist ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 3
Resurvey No. of Trip: 1

2) _____
Rep. Format: EZCLAIMS
Lump Sum 1800

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Wsel:nd (\$ _____)

Survey Fee: _____
Transportation: _____
\$ + RS. \$ _____
Photos _____
Others _____

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)

25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

To: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00 Springleaf Tower
Singapore 079909

Dear Sir / Madam:

RE: VEHICLE REPAIR ESTIMATE

Owner : KHOZEM ZAKI UDDIN DARUWALA

Model : HONDA CITY

Reg : 21/01/2011

Chassis : MRHGM26709P020534

DO Accident : 18/06/2023

THIRD PARTY CLAIM AGAINST

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE

27/06/2023

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	Front bumper	\$ 420.00	de
2	Front headlamp RH	\$ 510.00	cur
3	Front fender RH	\$ 360.00	bt
4	Front rim RH	\$ 750.00	art
5	Front bonnet	\$ 750.00	X
6	Front fender inner shield RH	\$ 75.00	de
7	Front fog lamp RH	\$ 510.00	X
8	Front fog lamp cover RH	\$ 75.00	X
9	Front bumper side retainer RH	\$ 90.00	de
Total Parts		\$ 3,705.00	
Less 20%		\$ 741.00	
		\$ 2,964.00	
11	Front fender inner shield clip	\$ 30.00	2over
12	Front bumper sensor	\$ 200.00	X
13	Front bumper clip	\$ 30.00	ney
14	To spray painting on the replaced and repair parts, prepare spray such as masking tape the unaffected areas with paper cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 600.00	480
15	To remove and replace the above damaged parts, straighten knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 480.00	300
16	To apply undercoating on the repaired and replaced panels for rust protection.		
17	To dismantle and refit front undercarriage.	\$ 120.00	X
18	To remove and refit front bumper sensor.	\$ 80.00	X
19	To computer wheel alignment	\$ 100.00	80

Tanfer 9249 5749/62565561
up 26/6/23C 1ph
L/S Resurvey after repair
Tanfer CThrauts.com
3days

Labour Total: \$ 1,640.00