

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio	nale Des Eynerts Fr	1 Automo	philes on the consequence
	INCOME INSURAN	JOE LTD	naic Des Experts Ei	Ref:	CS3/INC23000975/Tvp3
	75 BRAS BASAH F				<del>91/91/202</del> 8 21/06/2023
		SINGAPORE 189557		Date:	<del>01/01/202</del> 0 21/00/2020
	ATTN: KENNETH	НО		Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLG 7673H	Veh. Inspected	k	SNC 819Z
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1206885-002	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		31/01/2023 21/06/2023
2.		Vehicle Parti	culars & Condit	ion	
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3.		Conditi	ons of Tyres		
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
<b>1</b> .		Description	on of Damages		
5.	General Information				
	Accident Date	25/01/2023	Inspection Dat	e	31/01/2023
	Survey held at		OP		
	160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				