

Kenneth
96910863

Not Authorized
L1 Reg &
Repair After Rainy
5 days



Carz Auto Services Pte Ltd

61, Woodlands Industrial Park E9,
Premium@E9, #04-04, Singapore 757047
Tel: 6909 3080 Fax: 6909 3081 Email: claims@carzauto.com.sg
UEN/GST: 201409457D

Insurance: Allianz Insurance Singapore Pte Ltd

Address: 79 Robinson Road, #09-01, Singapore 068897

VEHICLE DETAILS			
Make:	Toyota	Vehicle No:	SKQ6522B
Model:	Altis	Date In:	28-6-2023
Chassis No:	MR053REH104518608	Date Out:	

ACCIDENT DETAILS			
Date:	26-06-23	Time:	7:35 AM
Location:	TPE TOWARDS CHANGI	Type:	Head to Head

Vehicle Repair Estimate - To be completed by ARC Service Advisor

S/N	Parts Description	Qty	Renew / Repair / Not Given	List Price (\$)	Part Discount	Final Price (\$)	Surveyor Pricing
1	REAR BUMPER	1	Renew	\$ 360.00	25%	\$ 270.00	\$ -
2	REAR BUMPER REINFORCEMENT	1	Renew	\$ 200.00	25%	\$ 150.00	\$ -
3	REAR BUMPER BRACKET	2	Renew	\$ 90.00	25%	\$ 135.00	\$ -
4	REAR BUMPER SIDE RETAINER, LH & RH	2	Renew	\$ 80.00	25%	\$ 120.00	\$ -
5	REAR BUMPER SIDE SEAL, LH & RH	2	Renew	\$ 70.00	25%	\$ 105.00	\$ -
6	REAR BUMPER REFLECTOR, LH & RH	2	Renew	\$ 60.00	25%	\$ 90.00	\$ -
7	PANEL SUB-ASSY, BODY LOWER BACK	1	Renew	\$ 396.00	25%	\$ 297.00	\$ -
8	QUARTER PANEL, LH	1	Renew	\$ 720.00	25%	\$ 540.00	\$ -
9	BOOTLID	1	Renew	\$ 470.00	25%	\$ 352.50	\$ -
10	BOOTLID CHROME GARNISH	1	Renew	\$ 200.00	25%	\$ 150.00	\$ -
11	BOOTLID WEATHER STRIP (BODY SIDE)	1	Renew	\$ 150.00	25%	\$ 112.50	\$ -
12	BOOTLID ARM ASSY, LH & RH	2	Renew	\$ 70.00	25%	\$ 105.00	\$ -
13	BOOTLID LAMP, LH & RH	2	Renew	\$ 225.00	25%	\$ 337.50	\$ -
14	TAILLAMP, LH & RH	2	Renew	\$ 245.00	25%	\$ 367.50	\$ -
15	LUGGAGE COMPARTMENT COVER	1	Renew	\$ 220.00	25%	\$ 165.00	\$ -
16	LUGGAGE COMPARTMENT TRIM COVER, LH	1	Renew	\$ 270.00	25%	\$ 202.50	\$ -
17	LOCK ASSY	1	Renew	\$ 255.00	25%	\$ 191.25	\$ -
18	STRIKER	1	Renew	\$ 35.00	25%	\$ 26.25	\$ -
19	REVERSE SENSOR (1 set)	1	Renew	\$ 288.00	25%	\$ 216.00	\$ -
20	REAR FLOOR FINISH, PLATE	1	Renew	\$ 190.00	25%	\$ 142.50	\$ -
21	REAR SHOCK ABSORBER ASSY, LH	1	Renew	\$ 170.00	25%	\$ 127.50	\$ -
23	EMBLEM (LOGO)	1	Renew	\$ 70.00	25%	\$ 52.50	\$ -
24	EMBLEM (COROLLA)	1	Renew	\$ 50.00	25%	\$ 37.50	\$ -
25	EMBLEM (ALTIS)	1	Renew	\$ 50.00	25%	\$ 37.50	\$ -
Total Parts Costs After Discount:						\$ 4,330.50	\$ -

Misc Costs

S/N	Special Nett Item - Description	Qty	Renew / Repair / Not Given	Net Price (\$)	Surveyor Pricing
1	LICENSED PLATE WITH CASING	1	Renew	\$ 60.00	\$ -
1	REAR BUMPER CLIPS	10	Renew	\$ 60.00	\$ -
Special Nett Cost:				\$ 60.00	\$ -

S/N	Labour Works / Panel Beating Related Works - Job Scope	Amount	Surveyor Pricing
1	TO RESPRAY ALL AFFECTED AREAS - \$300/PNL	\$ 1,200.00	\$ -
2	TO REMOVE/ REFIX WIRING CHECKS	\$ 60.00	\$ -



Carz Auto Services Pte Ltd

61, Woodlands Industrial Park E9,
Premium@E9, #04-04, Singapore 757047

Tel: 6909 3080 Fax: 6909 3081 Email: claims@carzauto.com.sg
UEN/GST: 201409457D

3	TO REMOVE/ REPLACE REVERSE SENSORS	\$ 60.00	500
4	TO TUFFCOAT AFFECTED AREA	\$ 60.00	✓
5	TO PERFORM COMPUTERISED FOUR WHEEL ALIGNMENT	\$ 120.00	X
6	TO REMOVE /REPLACE /REALIGN /RENEW ALL AFFECTED REAR DAMAGED PARTS - \$350/DAY	\$ 1,200.00	6000
TOTAL LABOUR COSTS:		\$ 2,700.00	\$ -
GRAND TOTAL:		\$ 7,090.50	\$ -
Type of Repair:		Lumpsum	\$ -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey damaged area after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: