

ASS. REC. BY:

REF:

A15/23008474/Ky

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of 10 Ad North Link 06-91

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$30k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKQ 6522B

Yr Regn:

12, 14

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

c.c.

1598

Colour

m. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

221017

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH104318608

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

26/6/23

D.O.I.

28/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Grot B1

3/7 61Pm @ 3200k Cahr

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

**Carz Auto Services Pte Ltd**

61, Woodlands Industrial Park E9,
 Premium@E9, #04-04, Singapore 757047
 Tel: 6909 3080 Fax: 6909 3081 Email: claims@carzauto.com.sg
 UEN/GST: 201409457D

Kennerth
 96910663

Not Notified
 11pm @ 3200h
 Preparing After Rainy
 5 days

Insurance: **Allianz Insurance Singapore Pte Ltd**

Address: 79 Robinson Road, #09-01, Singapore 068897

VEHICLE DETAILS							
Make:	Toyota			Vehicle No:	SKQ6522B		
Model:	Altis			Date In:	28-6-2023		
Chassis No:	MR053REH104518608			Date Out:			
ACCIDENT DETAILS							
Date:	26-06-23			Time:	7:35 AM		
Location:	TPE TOWARDS CHANGI			Type :	Head to Head		
Vehicle Repair Estimate - To be completed by ARC Service Advisor							
S/N	Parts Description	Qty	Renew / Repair / Not Given	List Price (\$)	Part Discount	Final Price (\$)	Surveyor Pricing
1	REAR BUMPER	1		\$ 360.00	25%	\$ 270.00	\$ -
2	REAR BUMPER REINFORCEMENT	1		\$ 200.00	25%	\$ 150.00	\$ -
3	REAR BUMPER BRACKET	2		\$ 90.00	25%	\$ 135.00	\$ -
4	REAR BUMPER SIDE RETAINER, LH & RH	2		\$ 80.00	25%	\$ 120.00	\$ -
5	REAR BUMPER SIDE SEAL, LH & RH	2		\$ 70.00	25%	\$ 105.00	\$ -
6	REAR BUMPER REFLECTOR, LH & RH	2		\$ 60.00	25%	\$ 90.00	\$ -
7	PANEL SUB-ASSY, BODY LOWER BACK	1		\$ 396.00	25%	\$ 297.00	\$ -
8	QUARTER PANEL, LH	1		\$ 720.00	25%	\$ 540.00	\$ -
9	BOOTLID	1		\$ 470.00	25%	\$ 352.50	\$ -
10	BOOTLID CHROME GARNISH	1		\$ 200.00	25%	\$ 150.00	\$ -
11	BOOTLID WEATHER STRIP (BODY SIDE)	1		\$ 150.00	25%	\$ 112.50	\$ -
12	BOOTLID ARM ASSY, LH & RH	2		\$ 70.00	25%	\$ 105.00	\$ -
13	BOOTLID LAMP, LH & RH	2		\$ 225.00	25%	\$ 337.50	\$ -
14	TAILLAMP, LH & RH	2		\$ 245.00	25%	\$ 367.50	\$ -
15	LUGGAGE COMPARTMENT COVER	1		\$ 220.00	25%	\$ 165.00	\$ -
16	LUGGAGE COMPARTMENT TRIM COVER, LH	1		\$ 270.00	25%	\$ 202.50	\$ -
17	LOCK ASSY	1		\$ 255.00	25%	\$ 191.25	\$ -
18	STRIKER	1		\$ 35.00	25%	\$ 26.25	\$ -
19	REVERSE SENSOR (1 set)	1		\$ 288.00	25%	\$ 216.00	\$ -
20	REAR FLOOR FINISH, PLATE	1		\$ 190.00	25%	\$ 142.50	\$ -
21	REAR SHOCK ABSORBER ASSY, LH	1		\$ 170.00	25%	\$ 127.50	\$ -
23	EMBLEM (LOGO)	1		\$ 70.00	25%	\$ 52.50	\$ -
24	EMBLEM (COROLLA)	1		\$ 50.00	25%	\$ 37.50	\$ -
25	EMBLEM (ALTIS)	1		\$ 50.00	25%	\$ 37.50	\$ -
Total Parts Costs After Discount:						\$ 4,330.50	\$ -

Misc Costs					
S/N	Special Nett Item - Description	Qty	Renew / Repair / Not Given	Net Price (\$)	Surveyor Pricing
1	LICENSED PLATE WITH CASING	1	Renew	\$ 60.00	\$ -
1	REAR BUMPER CLIPS	10	Renew	\$ 60.00	\$ -
Special Nett Cost:				\$ 60.00	\$ -
S/N	Labour Works / Panel Beating Related Works - Job Scope	Amount		Surveyor Pricing	
1	TO RESPRAY ALL AFFECTED AREAS - \$300/PNL	\$ 1,200.00		\$ 800.00	
2	TO REMOVE/ REFIX WIRING CHECKS	\$ 60.00		\$ 20.00	



Carz Auto Services Pte Ltd

61, Woodlands Industrial Park E9,
 Premium@E9, #04-04, Singapore 757047
 Tel: 6909 3080 Fax: 6909 3081 Email: claims@carzauto.com.sg
 UEN/GST: 201409457D

3	TO REMOVE/ REPLACE REVERSE SENSORS	\$ 60.00	501
4	TO TUFFCOAT AFFECTED AREA	\$ 60.00	✓
5	TO PERFORM COMPUTERISED FOUR WHEEL ALIGNMENT	\$ 120.00	X
6	TO REMOVE /REPLACE /REALIGN /RENEW ALL AFFECTED REAR DAMAGED PARTS - \$350/DAY	\$ 1,200.00	6001
TOTAL LABOUR COSTS:		\$ 2,700.00	\$ -
GRAND TOTAL:		\$ 7,090.50	\$ -
Type of Repair:		Lumpsum	\$ -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey or (re)after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: