

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/06/2023
User ID : CatherineLee

Section A - Accident Details		
Registration Number	SG5529Y	
Case Reference Number	BUS/05/23/7030	
Registration Date	6/11/2017	
Company Type	SMRT Buses Ltd	
Make	VOLVO	
Model	VOLVO	
Name of Driver	Murugan A.L. Pariasamy	
Type of Accident	Head to Rear	
Accident Date and Time	15/5/2023 9:43 AM	
Accident Reported Date and Time	8/6/2023 12:21 PM	
Is Surveyor Required?	No	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number		
Special Instruction to ARC, if any	SG5529Y - REAR PORTION PC3042D (TP) - INSURED WITH CHINA TAIPING	
Prepared Date and Time	24/6/2023 10:05 AM	
Chassis Number	YV3S4P922HA183452	
Mileage		
Work Shop		
Repair Completion Date and Time		
Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,240.00	\$0.00
Total Spray Cost	\$772.00	\$0.00
Total Spare Part Cost	\$99,567.82	\$0.00
Total Other Cost	\$2,000.00	\$0.00
TOTAL COST	\$106,579.82	\$0.00
Lump Sum Total	\$106,600.00	
Number of Repair Days	18.0	8-10 days
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	24/06/2023 10:39 AM	
Signature		Kenneth
Remarks		

Not Authorised

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/06/2023

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$4,240.00	31801.
Total Labour	\$4,240.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$772.00	6021.
Total Spray Painting & Panel Beating	\$772.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$500.00	(Bill) 800
TO ALIGN CHASSIS	\$1,000.00	601.
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$500.00	
Total Other Costs	\$2,000.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			ENGINE COMPLETE	1.00	\$90,000.00	10.00	\$81,000.00	Replace	✓
	Body	A11-00691	REAR END AIRCON DOOR	1.00	\$6,051.05	10.00	\$5,445.95	Replace	✓
		A11-00880	BOOT DOOR ASSEMBLY.RR ENG SER Dr 3 HINGE	1.00	\$4,149.78	10.00	\$3,734.80	Replace	By ✓
		A11-00710	TOP REAR SERVICE DOOR	1.00	\$3,095.05	10.00	\$2,785.55	Replace	By ✓
		DES-00227	GAS JACK STAY:530N;RR ENG DOOR (FOR A11-00880)	2.00	\$1,086.00	10.00	\$1,954.80	Replace	✓
		DEL-00625	BOLT.6" PLATED SPRING LOADED.DOOR (FOR A11-00865)	2.00	\$40.65	10.00	\$73.17	Replace	?
	VM	RSM-00111	RUBBER BUFFER	2.00	\$92.98	10.00	\$167.36	Replace	By ✓
	Body	B11-00081	REAR BUMPER PANEL	1.00	\$305.63	10.00	\$275.07	Replace	By ✓
	Body	B11-00082	REAR BUMPER PANEL	1.00	\$305.63	10.00	\$275.07	Replace	By ✓
	VE	ELU-00486	NUMBER PLATE LIGHT	1.00	\$145.40	10.00	\$130.86	Replace	By ✓
	Body	PLA-00798	NO PLATE RECESS PAN	1.00	\$321.15	10.00	\$289.03	Replace	By ✓
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	By ✓
		A11-00865	DOOR.LOWER BOOT	1.00	\$3,301.67	10.00	\$2,971.50	Replace	?
		ELU-00486	NUMBER PLATE LIGHT	2.00	\$216.48	10.00	\$389.66	Replace	By ✓
Total					\$109,186.47		\$99,567.82		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

For Auto Consultants hence notify the Repairer of the following:

- To ensure the repairer is aware of the damage to the vehicle.
- To ensure the repairer is aware of the damage to the vehicle.
- To ensure the repairer is aware of the damage to the vehicle.