MFORT TRANSPORTATION PTE LTD

EPAIR ESTIMATE

Model

Vehicle No.: SHC2314X : HYUNDAI Make

: IONIQ(G2)

Date: 24/06/2023 Insurance: INCOME MVA: MS. LOKE YY

161 .	101114(02)			the state of the same
Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	FRT BUMPER COVER	- Commercial programming and continued to		\$ 481.10 fr
10	FRT BUMPER CLIPS			\$ 22.00 aly
1	FRT BUMPER SIDE BRACKER LH			\$ 28.00
	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50 Kn
2	HEADLAMP LH			\$ 2,110.30
	FRT BUMPER SIDE MOULDING LH			\$ 93.60pm
:	1 DAY LIGHT LH			\$ 642.50
	1 FRT FENDER BLUE-DRIVE EMBLEM LH			\$ 26.60
	1 FRT WHEEL COVER LH			\$ 217.20 (2)
	1 FRT FENDER SHIELD LH		240	\$ 164.70
			644.80	
	SUB TOTAL		194.80	\$ 4,154.50
	LESS 20%		611.0	
	DISCOUNTED TOTAL			\$ 3,323.60
				\$ -
				i
	Labour Charge		262	2,-
	PANEL BEATING		860	\$ 750.00 35
	SPRAY PAINTING CHARGE			\$ 600.00 5
	CHECK ALL LIGHTING		1544.80	\$ 60.00
	TOTAL LABOUR			\$ 1,410.00
			1544.80 65\$1250 ~2days	
	ESTIMATE TOTAL		O laus	\$ 4,733.60
			"Lamp	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tauphin 97495749

WP No/6/173 C114v

2 days

Lls Newy cuffe pepair

Josephin C/Markin

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Cate.