

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SKX1909R

NOT Withash
L1 Sy &
Pricing After Painting
4-5 days

No.	Qty	Nett Items			
1	1	Rear bumper	\$ Bu	571.80	—
2	1	Rear bumper LH side reflector	\$	170.80	?
3	1 set	Rear bumper clips	\$ m	50.00	—
4	1	Rear LH corner cover	\$	172.80	?
5	1	Rear corner cover retainer	\$ sm	36.00	x
6	1	Rear LH wheel arch garnish	\$ Bu	185.00	—
7	1 set	Rear LH wheel arch garnish clips	\$ m	40.00	—
8	1	LH taillamp	\$	509.60	?
9	1	Rear tailgate	\$ R	1,290.00	—
10	1	Rear tailgate LH "VEZEL" emblem	\$ m	48.00	—
11	1	Rear tailgate LH lamp	\$ R	288.90	x
12	1	Rear tailgate top lock	\$ R	96.60	x
13	1	Rear tailgate weatherstrip	\$ R	115.60	x
14	1	Rear tailgate inner trim board	\$	285.00	?
15	1 set	Rear tailgate inner trim board clips	\$	60.00	?
16	1	Rear end panel	\$	399.40	?
17	1	Rear end panel top garnish	\$ R	192.30	x
18	1	Rear end panel keyless sensor	\$ R	195.30	x
19	1	Rear end panel buzzer	\$ R	65.70	x
20	1	Rear LH fender inner side garnish	\$ R	250.70	x
21	1	Rear spare tyre top board	\$ R	228.70	x
22	1	Rear under splash cover	\$	290.00	?

LKK Auto Consultants hence notify the Repairer of the following:

Special Net Items

23	1 set	Reverse sensors	• To display damaged part(s) during resurvey	\$	280.00	?
24	1	Rear number plate	• Parts prices are subject to confirmation	\$	50.00	x
25	1 set	Rear windscreen sealant	• Third party survey is on a "Without Prejudice" basis	\$	80.00	400.00
26	1 set	Rear end panel sealant	• No illegal modification(s) is allowed	\$	80.00	?
			• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	\$	80.00	?
			Total :	\$	490.00	

Acknowledged by Repairer

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00	?
2	To putty and spray Spray Paintings charges.	\$	1,000.00	500
3	To check wirings and lightings.	\$	40.00	200
4	To remove, refit rear windscreen glass.	\$	140.00	1200
5	To remove, refit reverse sensors.	\$	80.00	500
6	To remove, refit tailgate fittings.	\$	80.00	600
7	To remove, refit rear upholstery and attachments.	\$	120.00	?
8	To supply and apply anti rust treatment	\$	80.00	300
	Total :	\$	2,540.00	

Total Parts and Labour : \$ 8,572.20