MFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHA3241B

MAKE MODEL **HYUNDAI** IONIQ

DATE:

24.06.23

MVA JUMANI

DOA:

23.06.23

INCOME

Qty	Parts Description/ Labour	Туре	Unit Price	Amount	
	FRT BUMPER ASSY			\$481.10/	7
10	FRT BUMPER CHIPS			\$22.00 4 \$1,568.60	9
1	RADIATOR GRILLE				
1	FRT BUMPER CENTRE MOULDING			\$368.50 ⁴ \$31.30	20W
1	RADIATOR GRILLE EMBLEM			\$31.30	¢
			390.50		
	SUB TOTAL		312.40	\$2,471.50	
	LESS 20%	l.		\$494.30	
	DISCOUNTED TOTAL			\$1,977.20	
			*		
			cur	ČEE OO	NET
	FRT NUMBER PLATE		Wil	\$55.00	NET
				l.	INEI
	SUB TOTAL		55	\$55.00	NET
	300 TOTAL			\$33.00	INL
	Labour Charge				
	PANEL BEATING	1	35	\$400.00	
	SPRAY PAINT		25	ن \$300.00	
			600	42000	
			6016		
	TOTAL LABOUR		962.40	\$700.00	
			1 17 60		
	ESTIMATE TOTAL		450	\$2,732.20	
			967:40 C/59750 Jednys 14		
			() *		
			<u> </u>		
	This is an initial patients to				
	he prepared after the subject is a visual inspection of the	above vehi	cle. The final repair qua	intum will	
	This is an initial estimate based on a visual inspection of the	above vehi	cle. The final repair qua	intum will	

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

l'ale;