



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8608C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT DOOR OUTER HANDLE RH	BROKEN	234.80	234.80
1	FRT DOOR ASSY RH	BENT	1,797.20	1,797.20
1	FRT DOOR KEY COVER RH	MISSING	13.90	13.90
	LESS 20% DISCOUNT		-409.18	-409.18
			1,636.72	1,636.72
<b><u>NETT ITEMS</u></b>				
1	FRT DOOR COMFORT LOGO (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS LOGO (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-15.50
			155.00	139.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	ADVERTISEMENT LOGO-DOOR (SN)	CUT	200.00	200.00
1	ADVERTISEMENT LOGO-FENDER (SN)	NOT NECESSARY	100.00	-
			300.00	200.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		800.00	350.00
	SPRAY PAINT.		800.00	500.00
	CHECK WIRING.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	30.00
	REMOVE/REFIX DOOR PARTS.		120.00	60.00
			1,820.00	940.00
<b>GRAND TOTAL</b>			<b>3,911.72</b>	<b>2,916.22</b>

Report Ref No. NS/INC23006482/Tvp3m4

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,300.00</b>
---	--	--	-----------------

Report Ref No. NS/INC23006482/Tvp3m4



**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.