MFURTDELGRO ENGINEERING PTE LTD

EPAIR ESTIMATE*

VEHICLE NO MAKE

SH 8608C

HYUNDAI

IONIQ MODEL

DATE:

24.06.23

MVA JUMANI

DOA:

23.06.23

INCOME

		DOA.	23.00.23	HACCIVIL	
ty	Parts Description/ Labour	Туре	Unit Price	Amount	
	FRT DOOR OUTER HANDLE RH			\$234.80	ם אם
	FRT DOOR ASSY RH			\$1,797.20	
1	FRT DOOR KEY COVER RH			\$13.90	mil
	SUB TOTAL		2045.90	\$2,045.90	1
	LESS 20%		1636,72	\$408.18	
	DISCOUNTED TOTAL			\$1,636.72	
	FRT DOOR COMFORT LOGO		155 ni	\$75.00	NE
	REAR DOOR APPS LOGO		10/0- 139.50 W	\$80.00	NE
			(2/2/2/2		
	SUB TOTAL			\$155.00	NE
	Labour Charge		5/		
	PANEL BEATING		350	\$800.00	
	SPRAY PAINT			\$800.00	
	CHECK WIRING		Λ,	↑ × \$50.00	
	TUFF KOTE			\$50.00	
	REMOVE/REFIX DOOR PARTS			69 \$120.00	
	ADVERTISEMENT LOGO-DOOR	4	1140 m	\$200.00	ľ
	ADVERTISEMENT LOGO-FENDER		2911 22 N	n× \$100.00	j
	TOTAL LABOUR		2916,22	\$2,120.00	
			45\$2300		1
	ESTIMATE TOTAL		•	\$6,759.32	1
			· 2days &		1
			J		
j	This is an initial estimate based on a visual inspection of the	above veh	icle. The final renair ou	antum will	1

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Tup hanged by a motor surveyor appointed by

Tup hanged by a motor surveyor appointed by

Tup hanged by a motor surveyor appointed by

Up, 2 dup

Up, 2 du

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: