

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0603/2023/EQ
DATE : 28-Jun-23
WIP : 26731

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SMU 2458 K**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : M/S TEN-LEAGUE PORT ENGINEERING SOLUTIONS PTE.LTD
ADDRESS : 16 GUL DRIVE
SINGAPORE 629467

TELEPHONE : HP +65 91559099
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPG23001400
VEHICLE NO : **SMR 9456 K**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 31/1/2020
ENGINE NO : CVK 082956
CHASSIS NO : WAUZZZF48KA079374
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jun-23
PLACE OF ACCIDENT : BUKIT BATOK WEST AVE. 5, SINGAPORE
AT ESSO PETROL STATION

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 9456 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✗	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 500	
4	TO RESPRAY FRONT BUMPER.	\$ 900.00 550	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,972.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 9456 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Repair</i>	1	\$ 2,515.00	X	
2	FRONT BUMPER FIXING PARTS	1	\$ 641.00	X	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 84.00	X	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 231.00	X	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 269.00	X	
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 150.00	X	
7	RADIATOR GRILLE <i>Crashed</i>	1	\$ 1,541.00		
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 159.00	X	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 147.00	X	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 953.00	X	
11	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	X	
12	FRONT BUMPER TOP COVER	1	\$ 151.00	X	
13	OIL COMPLY WITH VW STANDARD STICKER	1	\$ 14.00	X	
14	CAUTION STICKER	1	\$ 17.00	X	
15	AIR CONDITIONER STICKER	1	\$ 9.00	X	
16	FRONT BUMPER BRACKET	1	\$ 163.00	X	
17	FRONT BUMPER SUPPORT - LH / RH	2	\$ 68.00	X	
18	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	X	
19	FRONT PARKING AID SEAL RING	4	\$ 11.00	X	
20	HEADLIGHT - RH	1	\$ 8,787.00	X	
SUB TOTAL SPARE PARTS		:	\$ 16,496.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 9456 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER - RH <i>Ne m</i>	1	\$ 244.00	X
22	LIFT CYLINDER CORRUGATED PIPE	1	\$ 111.00	X
23	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	X
24	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 76.00	X
25	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 50.00	X
26	RADIATOR AIR GUIDE - UPPER	1	\$ 25.00	X
27	RADIATOR AIR GUIDE - LOWER	1	\$ 38.00	X
28	FRONT NUMBER PLATE <i>AX 432 New</i>	S/N	\$ 60.00	X
29	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 17,622.00	
TOTAL LABOUR CHARGES		:	\$ 2,972.00	
GRAND TOTAL		:	\$ 20,594.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Adrian S
28/06/23

Not Authorised, 03 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT