



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDA1800Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 10821
Reg No/Reg Date SDA1800Z / 20/12/2017
Date In/Mileage
Chassis No WDD2130422A324699
Engine No 27492031218041
Make/Model MB/MB-E 200 2.0 SEDAN (W213) "EXCLUSIVE/
Colour/Trim 029 997 Kallaitte Gr/ 048 801 Leather Bla

| Account No | Terms | Date/Time Printed | CSE | Operator |
|---------------------------------|--------|-------------------|-------|------------------------|
| WA000001 | Credit | 26/06/2023/ 20:15 | AQ | 305 / Alan Quek Ai Lun |
| Description of Goods / Services | | | | |
| | Qty | Unit Price | Disc% | Amount |

M BPNSUN
POLICY NO/ACC DATE : 1700089793 / 22-06-2023
DRIVE IN: 23-06-2023 / TP CAR NO: SNA6541U (ALLIANZ INS)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

| | | | | | |
|--|------|---------|-------|------|---------|
| A BPILAB | | | | 0.10 | 380.00 |
| USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT | | | | | |
| A BPILAB | | | | | 120.00 |
| BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS.NETT | | | | | |
| A BPILAB | | | | | 180.00 |
| CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM.NETT | | | | | |
| A BPILAB | | | | | 1440.00 |
| REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR FOR NECESSARY REPAIR. | | | | | |
| A BPILAB | | | | | 5760.00 |
| REMOVE & REPLACE REAR BUMPER, REAR BOOT LID, REAR END PANEL & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH. | | | | | |
| A BPIRES | | | | | 4500.00 |
| RESPRAY REAR BUMPER, REAR BOOT LID, REAR END PANEL, REAR LEFT FENDER & REAR RIGHT FENDER | | | | | |
| M REAR BUMPER | 1.00 | 1587.48 | 00.00 | | 1587.48 |
| M REAR BOTTOM PANEL | 1.00 | 389.53 | 00.00 | | 389.53 |
| M REAR BOTTOM PANEL GARNISH | 1.00 | 402.10 | 00.00 | | 402.10 |
| M LH/R BUMPER GARNISH | 1.00 | 174.98 | 00.00 | | 174.98 |
| M RH/R BUMPER GARNISH | 1.00 | 174.98 | 00.00 | | 174.98 |
| M CT/R BASIC MOUNTING FOR BUMPER | 1.00 | 154.56 | 00.00 | | 154.56 |
| M LH/R BASIC MOUNTING FOR BUMPER | 1.00 | 88.08 | 00.00 | | 88.08 |
| M RH/R BASIC MOUNTING FOR BUMPER | 1.00 | 74.45 | 00.00 | | 74.45 |
| M CT/R PARKING SENSOR | 1.00 | 205.45 | 00.00 | | 821.80 |
| M CT/R PARKING SENSOR SEAL | 1.00 | 7.85 | 00.00 | | 31.40 |
| M LH/R BUMPER REFLECTOR | 1.00 | 42.09 | 00.00 | | 42.09 |
| M RH/R BUMPER REFLECTOR | 1.00 | 42.09 | 00.00 | | 42.09 |

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be
required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur,
we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring
removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDA1800Z

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 10821
Reg No/Reg Date SDA1800Z / 20/12/2017
Date In/Mileage / 0
Chassis No WDD2180422A324699
Engine No 27492031218041
Make/Model MB/MB E 200 2.0 SEDAN (W213) "EXCLUSIVE/
Colour/Trim 029 997 Kallaitte Gr/ 048 801 Leather Bla

SDA1800Z

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|------------------------|
| WA000001 | Credit | 26/06/2023/ 20:15 | AQ | 305 / Alan Quek Ai Lun |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--------------------------------------|------|------------|-------|---------|
| M REAR PARKING SENSOR WIRING HARNESS | 1.00 | 565.45 | 00.00 | 565.45 |
| M REAR BOOT LID | 1.00 | 2990.61 | 00.00 | 2990.61 |
| M REAR BOOT LID SEAL | 1.00 | 248.33 | 00.00 | 248.33 |
| M E200 EMBLEM | 1.00 | 154.24 | 00.00 | 154.24 |
| M REAR STAR EMBLEM | 1.00 | 55.41 | 00.00 | 55.41 |
| M REAR BOOT LID MOULDING | 1.00 | 197.59 | 00.00 | 197.59 |
| M REAR BOOT LID LOCK | 1.00 | 398.93 | 00.00 | 398.93 |
| M REAR CROSS MEMBER | 1.00 | 1039.80 | 00.00 | 1039.80 |
| M REAR END PANEL | 1.00 | 1982.22 | 00.00 | 1982.22 |
| M GROMMET | 3.00 | 2.73 | 00.00 | 8.19 |
| M SEAM SEALANT | 1.00 | 116.42 | 00.00 | 116.42 |
| M CAVITY SEALANT | 1.00 | 116.39 | 00.00 | 116.39 |
| M TWO-COMPONENT ADHESIVE | 1.00 | 118.43 | 00.00 | 118.43 |
| M ADHESIVE SEALANT | 1.00 | 904.72 | 00.00 | 904.72 |

ESTIMATE

Rahul
Up 9001068
10 days
28/06/23 @ 1180
Reg by part

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Authorized signatory and company stamp

Nett 25,260.27
8% GST on 25260.27 2020.82

Total Payable 27,281.09

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG