

A.S.S. REG. BY: Taught

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC8342A Yr Regn: 20/8 / Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Hyundai Carig c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 499692 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1MHC851CVK4122282

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 27/6/23

Survey held at

Comfort Logg

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

Frt + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Data/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. / T. _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

LKK-

DATE: 26.06.2023

SLD6605C

INSURANCE: INCOME (L/S)

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHC8342A

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Front Bumper	1		\$ 481.10	de
	Front Bumper Upper Moulding	1		\$ 368.50	X
	Front Bumper Clips	10	\$ 2.20	\$ 22.00	44
	Front Bumper Side Brkt LH	1		\$ 35.00	?
	Front Wheel Cap LH	1		\$ 346.40	X
	Front Fender LH	1		\$ 588.80	X
	Front Fender (Blue-Drive) LH	1		\$ 26.60	X
	Front Fender Shield LH	1		\$ 164.70	X
	HeadLamp LH	1		\$ 2,110.30	X
	DayLight LH	1		\$ 642.50	X
	DayLight Grille LH	1		\$ 93.45	X
	SUB TOTAL			\$ 4,879.35	
	LESS 20%			\$ 975.87	
	TOTAL SPARE PARTS			\$ 3,903.48	
	Front Fender Adv.Sticker LH	1		\$ 100.00	NETT
	Labour Charge				
	Panel Beating			\$ 800.00	350
	Spray Painting			\$ 600.00	250
	Check Wirings			\$ 40.00	X
	Tuff Kote			\$ 60.00	X
	Wheel Alignment			\$ 120.00	X
	TOTAL LABOUR			\$ 1,620.00	
	ESTIMATE TOTAL			\$ 5,623.48	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. the Repairer of the following:

Tanjun 97495741
 WP' 27/6/23 @ 1030m
 L/S Rising after repair
 2 days
 Tanjun @ Kuantan

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Hyundai Ioniq

Date/Time: 26.06.2023 13:41

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 5901671

JC NO305558833

OMER

REGN NO.:

SHC8342A

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN

26.06.2023 09:45

YR OF MANU.

11.12.2018

TARGET DATE

CHASSIS CODE

KMHC851CVKU122282

COMPLETION DATE/TIME:

JNT CARD NO.

JOB DESCRIPTION

cident Date: 24.06.2023

PURE: 3P 24.06.2023

NO


0010

LABOR CODE

PB

DESCRIPTION

LUMPSUM REPAIR-SHC8342A-TP



JO & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ement Slip

Exit Pass

SHC8342A

LIMITS

Vehicle No.:

SHC8342A

vice Advisor

Signature/Date

Name of Service Advisor

Date

ad to Service Reception upon collection

To be kept by Security Guard