

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/23006517/Uq3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMG 6817E

at Workshop m/s C & C ub, 10am

of _____

Insured: GBE9998L

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8110k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

154A

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 39886

Veh No: SMG 6817E Yr Regn: 28/12/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: KIA Sorento c.c 2199

Colour: Brown A/C: Insured / Std / NI / NA

Sp.Reading: 86597 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAPH81BM J5465512

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/60R18

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 26/06/23 D.O.I. 28/06/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Day 18k.

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	154A
Vehicle Details	
Vehicle No.:	SMG6817E
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2023
Vehicle Make:	KIA
Vehicle Model:	SORENTO 2.2(8AT) CRDI 2WD S/R
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	D4HBJH374397
Chassis No.:	KNAPH81BMJ5465512
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$27,500.00
Original Registration Date:	28 Dec 2018
First Registration Date:	28 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$30,500.00 15740
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2028
PARF Rebate Amount:	\$22,875.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$30,959.00
COE Rebate Amount:	\$17,011.00
Total Rebate Amount:	\$39,886.00

The information contained herein is correct as at 28 Jun 2023

OK

Car Accessories & Products

Pimping up your ride? Browse thousands of car products for even more choices! Read honest reviews by our trusted consumers before you make a purchase.

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate
GV Automobile Centre StarAd

ABWIN 論壇

» Visit Our Profile «

Sort by Date Posted 20 results/page

2 vehicles



Kia Sorento

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Kia Sorento		Any	Any	2018	Any	Any	Any	Available
	Kia Sorento	Kia Sorento Diesel 2.2A CRDi Sunroof	\$102,888	\$17,730 /yr	06-Jun-2018	2,199 cc	96,890 km	SUV	Available
		Fuel Type: Diesel (Euro 5 Engine and Above) The sorento diesel is the ultimate SUV for those who demand power and efficiency. Its 2.2-liter diesel engine delivers impressive torque...							
		Carro							
		Posted: 22-Jun-2023							
	Kia Sorento	Kia Sorento Diesel 2.2A CRDi Sunroof	\$115,000	\$19,960 /yr	26-Jun-2018	2,199 cc	51,500 km	SUV	Available
		Fuel Type: Diesel (Euro 5 Engine and Above) Extremely well maintained and in pristine condition by current owner, Low Mileage, High loan available with lowest interest rates. Trade...							
		Posted: 21-Jun-2023							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Buy / Rent Cars

New Cars For Sale

Used Cars For Sale

Cars For Rent

Sell Your Car

Post an Ad

Sell by Bidding

Sell by Consignment

Aftermarket

Workshop Directory

Aftermarket Products

Articles

Car Repair

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YEO TONG YONG	Cust No/Name /YEO TONG YONG
BLK 218B BOON LAY AVENUE	Reg No/Reg Date SMG6817E / 28/12/201
#09-277	Date In/Mileage 26/06/2023/ 86454
SINGAPORE 642218	Chassis No KNAPH81BMJ5465512
Contact No Mobile: 96820559	Engine No D4HBJH374397
	Make/Model KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	26/06/2023/ 14:27	REN	979 / Renemer Ramirez Bag	20921
Description of Goods / Services				Qty	Unit Price Disc% Amount
Z TEXT					
ACCIDENT ON 26/06/2023 ALONG PIE TOWARDS CHANGI BEFORE 20B EXIT					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT VEHICLE					
TP#: GBE9998L TP INS: CHINA TAIPING					
A 10028901					280.00
TO CARRY OUT DIAGNOSTIC CHECK ON KDS AND CLEAR TROUBLE CODE					
A 90000001					80.00
TO CHECK WIRING AND ELECTRICAL SYSTEM					
E PNT88000					320.00
TO REPLACE TAILGATE GLASS					
E PNT88000					220.00
TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS					
E PNT88000					640.00
TO TRANSFER TAILGATE COMPONENTS & MECHANISM					
E PNT88000					640.00
TO REMOVE & RE-INSTALL FLOOR BOARDS,CARPETS & TRIMS TO FACILITATE					
REPAIR ON REAR ACCIDENT AFFECTED AREAS					
E PNT88000					2560.00
TO REPLACE EMBLEM,LOGO,TAILGATE,TAIL LAMPS,UPR & LWR REAR BUMPERS,SKID					
PLATE,CLIPS,BRACKETS,SENSORS,TOW COVER,SIGNAL LAMPS & COVERS,ETC					
TO REPAIR REAR END PANEL					
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000					2200.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					
(TAILGATE,UPR REAR BUMPER & REAR END PANEL)					
E PNT88000					100.00
TO CHECK & TEST REVERSE SENSORS					
M SUNDRY					100.00
TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS					
M SUNDRY					200.00
TO APPLY BODY SEALANT ON NEW PANELS					
M SUNDRY					200.00

Confirm & accepted by

not Authorised
28/6/23
whisper the party.
5 days

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YEO TONG YONG	Cust No/Name /YEO TONG YONG
BLK 218B BOON LAY AVENUE	Reg No/Reg Date SMG6817E / 28/12/201
#09-277	Date In/Mileage 26/06/2023/ 86454
SINGAPORE 642218	Chassis No KNAPH81BMJ5465512
Contact No Mobile: 96820559	Engine No D4HBJH374397
	Make/Model KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	26/06/2023/ 14:27	REN	979 / Renemer Ramirez Bag	20921		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
TO APPLY ANTI-CORROSION ON AFFECTED AREAS							?
M SUNDRY							50.00
TO SUPPLY REAR LICENSE PLATE WITH FRAME							
M SUNDRY						1.00	50.00
TO SUPPLY C&C BADGE							
M SUNDRY						1.00	50.00
TO SUPPLY TURBO EMBLEM (OWNER PURCHASED)							
M SUNDRY						1.00	50.00
SUNDRIES							
M GLASS ASSY-TAIL GATE				1.00	600.00	00.00	600.00
M LOGO ASSY-KIA SUB				1.00	60.00	00.00	60.00
M EMBLEM-SORENTO				1.00	28.00	00.00	28.00
M EMBLEM-ECO DYNAMICS				1.00	37.00	00.00	37.00
M PANEL ASSY-TAIL GATE				1.00	1479.00	00.00	1479.00
M LH OTR LAMP ASSY-REAR COMB				1.00	538.00	00.00	538.00
M LH INR LAMP ASSY-REAR COMB				1.00	855.00	00.00	855.00
M RH OTR LAMP ASSY-REAR COMB				1.00	544.00	00.00	544.00
M RH INR LAMP ASSY-REAR COMB				1.00	855.00	00.00	855.00
M UPR COVER-RR BUMPER				1.00	632.00	00.00	632.00
M LWR COVER-RR BUMPER				1.00	623.00	00.00	623.00
M SKID PLATE-RR BUMPER				1.00	103.00	00.00	103.00
M CLIP-BUMPER				10.00	1.00	00.00	10.00
M LH SIDE BRACKET ASSY-RR BUMPER				1.00	22.00	00.00	22.00
M RH SIDE BRACKET ASSY-RR BUMPER				1.00	22.00	00.00	22.00
M ULTRASONIC SENSOR-S.P.A.S				4.00	187.00	00.00	748.00
M OTR ULTRASONIC SENSOR-S.P.A.S				2.00	187.00	00.00	374.00
M LH COVER-BLANKING RR FOG				1.00	44.00	00.00	44.00
M LH LAMP ASSY-REAR FOG & R/REFL				1.00	134.00	00.00	134.00
M RH COVER-BLANKING RR FOG				1.00	44.00	00.00	44.00
M RH LAMP ASSY-REAR FOG & R/REFL				1.00	134.00	00.00	134.00
M CAP-RR HOOK				1.00	5.00	00.00	5.00
M UNDER COVER ASSY-RR BPR				1.00	30.00	00.00	30.00
M RAIL ASSY-REAR BUMPER				1.00	392.00	00.00	392.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YEO TONG YONG	Cust No/Name /YEO TONG YONG
BLK 218B BOON LAY AVENUE	Reg No/Reg Date SMG6817E / 28/12/201
#09-277	Date In/Mileage 26/06/2023/ 86454
SINGAPORE 642218	Chassis No KNAPH81BMJ5465512
Contact No Mobile: 96820559	Engine No D4HBJH374397
	Make/Model KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	26/06/2023/ 14:27	REN	979 / Renemer Ramirez Bag	20921

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M ANTENNA ASSY-SMARTKEY	1.00	53.00	00.00	53.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett	16,106.00
8% GST on	1288.48
Total Payable	17,394.48

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.