

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
00 SUPER WASTE MANAGEMENT PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:	MA030717	Date of Loss:	22/06/2023
Vehicle Reg. No.:	EL9323L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	BEH CHUN NGEE		
Make/Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Vehicle Reg. Date:	29/12/2015
Vehicle Colour:	Black		
Engine No:	HRA2215906A	Chassis No:	SJNFEAJ11U1542487
Odometer:	0 KM		
Paint Type:			
List Item Discount:	35.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	1,200.00
Labour	5,420.00
Paintwork Labour	0.00
Towing	120.00
Gross Total (S\$)	6,740.00
+ GST 8.00% (S\$)	539.20
Nett Amount (S\$)	7,279.20

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jun 2023)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merlimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/EL9323L/26/06/2023 17:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Handwritten signatures and initials:
 48
 K...
 +TP...

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT RH DOOR <i>repair</i>	35.00	0.00	-
2	1		*FRT RH DOOR HINGE UPPER <i>X</i>	35.00	0.00	-
3	1		*FRT RH DOOR HINGE LOWER <i>X</i>	35.00	0.00	-
4	1		*FRT RH DOOR RUBBER <i>X</i>	35.00	0.00	-
5	1		*FRT RH DOOR LOCK ASSY <i>X</i>	35.00	0.00	-
6	1		*FRT RH DOOR OUTER HANDLE ASSY <i>scd</i>	35.00	0.00	-
7	1		*REAR RH DOOR <i>TDN</i>	35.00	0.00	-
8	1		*REAR RH DOOR OUTLET PROTECTOR <i>MIS</i>	35.00	0.00	-
9	1		*REAR RH DOOR GLASS REGULATOR <i>?</i>	35.00	0.00	-
10	1		*REAR RH DOOR GLASS <i>X</i>	35.00	0.00	-
11	1		*REAR RH DOOR INNER TRIM BOARD <i>?</i>	35.00	0.00	-
12	1		*REAR RH DOOR LOCK ASSY <i>TDN</i>	35.00	0.00	-
13	1		*REAR RH DOOR RUBBER <i>scd</i>	35.00	0.00	-
14	1		*REAR RH DOOR GLASS OUTER CHROME <i>scd</i>	35.00	0.00	-
15	1		*REAR RH QUARTER GLASS <i>scd</i>	35.00	0.00	-
16	1		*REAR RH FENDER <i>buc</i>	35.00	0.00	-
17	1		*PETROL TANK COVER <i>scd</i>	35.00	0.00	-
18	1		*REAR RH FENDER ARC GARNISH <i>TDN</i>	35.00	0.00	-
19	1		*REAR RH BUMPER ARC GARNISH <i>TDN</i>	35.00	0.00	-
20	1		*REAR RH INNER FENDER SHIELD <i>TDN</i>	35.00	0.00	-
21	1		*REAR RH DOOR OUTER HANDLE ASSY <i>scd</i>	35.00	0.00	-
22	1		*REAR QUARTER GLASS OUTER CHROME <i>scd</i>	35.00	0.00	-
23	1		*REAR RH SHOCK ABSORBLE <i>X</i>	35.00	0.00	-
24	1		*REAR RH SHOCK ABSORBLE MOUNTING <i>X</i>	35.00	0.00	-
25	1		*REAR RH BEARING <i>?</i>	35.00	0.00	-
26	1		*REAR RH AXLE ARM <i>X</i>	35.00	0.00	-
27	1		*REAR RH WHEEL SENSOR <i>?</i>	35.00	0.00	-
28	1		*REAR RH DOOR INNER ARC C PANEL <i>?</i>	35.00	0.00	-
<i>REAR BUMPER</i>						
Total Parts (S\$)						0.00

Cheng Auto Bodyworks/EL9323L/26/06/2023 17:32. Not valid without Reference section.
 Generated using Merlimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BUMBER CLIPS <i>m✓</i>	30 100.00
2	1	INNER FENDER SHIELD CLIPS <i>m✓</i>	30 100.00
3	1	QUATER GLASS SEALANT <i>m✓</i>	40 100.00
4	1	REAR FENDER SEALANT <i>m✓</i>	80 200.00
5	1	REAR RH DOOR B ARC PANEL SEALANT <i>m✓</i>	80 200.00
6	1	TYRE <i>cut✓ 70%</i>	350 500.00
Sub Total (S\$)			1,200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR	New <i>100</i>	1,800.00
2	SPRAYPAINTING	New <i>800</i>	1,800.00
3	TO DOWN PETROL TANK TO FACILITATE REPLACE REAR FENDER	New <i>100</i>	500.00
4	REMOVE AND REINSTALL INNER SEAT LINING AND/OR UPHOLSTERY TO FACILITATE REPAIRS	New <i>100</i>	500.00
5	REMOVE AND REPLACE QUARTER GLASS	New <i>60</i>	100.00
6	ANTI-RUST COATING AND APPLY CORROSION PROTECTION	New <i>60</i>	100.00
7	REMOVE AND REPLACE/REFIT UNDERCARRIAGE: PER SIDE (FRONT/REAR); WHOLE FRONT WITH SUB-FRAME; WHOLE REAR WITH AXLE	New <i>100</i>	300.00
8	ALIGNMENT	New <i>60</i>	120.00
9	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New <i>80</i>	200.00
Gross Labour Cost (S\$)			5,420.00

Cheng Auto Bodyworks/EL9323L/26/06/2023 17:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram
Hp 90010068
12 days
43
28/06/23 201420
Resy after repair