



# HKL LIM TEAM MOTORSPORT PTE LTD

UEN: 202218929Z

Blk 1008 #01-24 Bukit Merah Lane 3, Singapore 159722.

Tel: 6275 6656 Email: hklteam@gmail.com

## FBK2605K

1	FRONT FORK ASSY LH/RH	\$700 X
2	FRONT FORK UNDER BRACKET	\$450 X
3	STEERING CONE BEARING	\$150 X
4	BODY FRAME ALIGNMENT	<i>Photo</i> \$750 <del>12</del> 240360
5	FRONT FENDER	\$190 X
6	HEAD COWLING	\$480 <i>cut</i>
7	FRONT SIGNAL LH/RH	\$240 X
8	HANDLE BAR	\$240 ?
9	HANDLE BAR BALANCER RH	\$30 <i>cut</i>
10	BRAKE LEVER RH	\$60 <i>cut</i>
11	SIDE MIRROR RH	\$90 <i>cut</i>
12	LOWER COWLING RH	\$160 <i>cut</i>
13	FRONT FOOT REST RH PANEL	\$190 <i>cut</i>
14	TAIL LIGHT	\$250 <i>cut</i>
15	REAR WHEEL RIM	\$550 ?
16	TAILBOARD LH/RH	\$480 <i>RA cut</i>
17	REAR NO PLATE	\$20 <i>bf</i>
18	REAR NO PLATE LIGHT	\$45 & ?
19	LOWER CENTER PANEL	\$120 <i>cut</i>
20	TOP BOX	\$180 <i>cut</i>
21	TAIL PANEL TOP	\$150 <i>cut</i>
22	TAIL PANEL BOTTOM	\$160 <i>cut</i>
23	REAR FENDER	\$98 <i>cut</i>
24	REAR WHEEL SHAFT	\$320 ?
25	REAR WHEEL BEARING \$60X2	\$120 ?
26	REAR WHEEL OIL SEAL	\$20 ?
27	GEAR BOX COVER GASKET	\$35 ?
28	EXHAUST HEADER	\$190 ?
29	EXHAUST HEADER GASKET	\$15 <i>na</i>
30	EXHAUST MUFFLER	\$1,800 <i>bf</i>
31	EXHAUST MUFFLER COVER	\$150 <i>cut</i>
32	EXHAUST MUFFLER END CAP	\$80 <i>cut</i>
33	EXHAUST MUFFLER GUARD	\$45 ?
34	EXHAUST HEADER GUARD	\$45 ?
35	EXHAUST MUFFLER GASKET	\$35 ?
36	REAR SUSPENSION LH/RH	\$400 ?

37	REAR BRAKE DISC	\$220 ✓
38	ENGINE MOUNTING BRACKET	\$220 ?
39	REAR SUSPENSION BRACKET	\$250 <i>ana</i>
40	TOWING	\$40 ✓
41	LABOUR	\$780 450

**TOTAL AMOUNT:**

**\$10,548**

*Tanfin 97445749 / 62563861*  
*WP 3.16/230 425*  
*CLS Resurvey after repair*  
*Tanfin & Lkhantson*  
*4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: