

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/LIP 23006527/4943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SA 1 / 5641

at Workshop m/s Sum pte Ltd

of _____

Insured: SM 49086

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 885k

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 4

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SA 1 / 5641

Yr Regn: 20/01/12

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: BMW

116

c.c

1598

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 116905

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W3A1A12060E948276

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40Zr18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Adventi

Front 6

Rear 6

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 26/06/23

D.O.I. 27/6/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

207 10k.
62000 31-12-2031 LTA 643038

7/7/23 2/5 6200 (Red 10996.05, 64%)
2/5 6000 (Red 11196.05, 65%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 6200

SQM Pte.Ltd

not Authorised

27/6/23

4/5 @ 6000/

Date: 26/06/2023

4 days.

Take photo After repair

To: Motor Claims Department

Vehicle No: SGY564A

Model: BMW 116I

Estimated Repair Cost For SGY564A BMW 116I

QTY	Parts	Amount
1	Front bumper <i>cut / to L1 ✓</i>	992 \$ 1,289.52 ✓
2	Front bumper side retainer @ \$48 <i>n/s one 1pc</i>	42 \$ 96.00 1pc
1	Front bumper logo <i>new</i>	98.00 \$ 100.85 ✓
1	Lh foglamp <i>one</i>	316.05 \$ 380.00 ✓
1	Lh foglamp garnish <i>1pc</i>	\$ 135.00 x
2	Headlamp @\$1997 <i>n/s one 0/5 11</i>	1893.05 \$ 3,996.00 1pc
2	Headlamp lower bracket @\$75 <i>1pc</i>	\$ 150.00 x
1	Radiator support panel <i>1pc x</i>	\$ 1,150.00 x
1	Lh ftr fender <i>1pc</i>	\$ 945.50 x
1	Lh ftr fender inner shield <i>1pc</i>	\$ 185.50 x
1	Lh ftr wheel bearing <i>Page</i>	509.10 \$ 543.73 ✓
1	Lh ftr knuckle arm <i>Page</i>	522.30 \$ 684.64 ✓
1	Lh ftr lower arm <i>Beut</i>	284.90 \$ 386.60 ✓
1	Lh ftr shock absorber <i>1pc x</i>	\$ 553.02 x
1	Lh ftr shock absorber top mounting <i>1pc x</i>	\$ 216.26 x
1	Lh wing mirror assy <i>cut / Page</i>	998.35 \$ 1,785.85 ✓
1	Lh rocker panel skirt <i>1pc x</i>	\$ 850.00 x
Parts Sum:		\$ 13,448.47
Parts Less 5% :		\$ 672.42
Parts Total:		\$ 12,776.05

Special Nett Items

1	Bumper lower skirt <i>Be/wrapped</i>	\$ 600.00 300
1	Front bumper clips <i>1pc 30</i>	\$ 50.00 30
1	Front bumper rivets <i>1pc 30</i>	\$ 50.00 30
1	Lh ftr fender inner shield clips <i>1pc x</i>	\$ 50.00 x
1	Lh ftr rim <i>cut 680</i>	\$ 800.00 650
1	Front number plate <i>1pc</i>	\$ 50.00 x
Special Nett Items Total:		\$ 1,600.00

Labour & Misc Charges

Description	Amount
To Check Wiring	\$ 50.00 20
To Diagnose/Reset/reprogram	\$ 11 280.00 X
Anti-rust	\$ 11 120.00 X
Replace front undercarriage	\$ 350.00 150
Computerise wheel alignment	\$ 120.00 80
Labour to remove necc parts, cut and reweld panel	\$ 900.00 400
Spray painting	\$ 1,000.00 550
Labour Charges Total:	\$ 2,820.00

Parts Total: \$ 12,776.05
Special Nett Items Total: \$ 1,600.00
Labour Charges Total: \$ 2,820.00
Total Cost Of Repair: \$ 17,196.05
(Non-Inclusive of GST)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5653-75
52
P- 5372-96
S. N- 1010
2 - 1200
7582.96
252
6066