

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/LIP 23006527/4943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SA 1 / 5049at Workshop m/s Sam pte Ltd

of _____

Insured: SM 49086

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 88k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

9.51
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SA 1 / 5049 Yr Regn: 20/01/12Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA 1Make: BMW 116! c.c. 1598Colour: Black A/C: Insured / Std / NI / NASp. Reading: 116905 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA1A12060E 948276Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or offBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40Zr18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or AdventiFront 6 mm Rear 6 mm

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/06/23 D.O.I. 27/6/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RtdThe U/C / Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction 27/10/12Coluati 31-12-2031 LTA 8430382/5 6200 Ured 10996.05, 64%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : TPLump Sum / I.B.L. (\$) 6200

SQM Pte.Ltd

not Authorised

27/6/23

1/s 62001

Date: 26/06/2023

4 days.

Take photo After repair

To: Motor Claims Department

Vehicle No: SGY564A

Model: BMW 116I

Estimated Repair Cost For SGY564A BMW 116I

QTY	Parts	Amount
1	Front bumper <i>cut / toli ✓</i>	992 \$ 1,289.52 ✓
2	Front bumper side retainer @ \$48 <i>n/s one 1pc</i>	42 \$ 96.00 1pc
1	Front bumper logo <i>nei ✓</i>	98.00 \$ 100.85 ✓
1	Lh foglamp <i>one</i>	316.05 \$ 380.00 ✓
1	Lh foglamp garnish <i>11</i>	\$ 135.00 x
2	Headlamp @\$1997 <i>n/s one 0/5 11</i>	1893.05 \$ 3,996.00 1pc
2	Headlamp lower bracket @\$75 <i>PPA</i>	\$ 150.00 x
1	Radiator support panel <i>11 x</i>	\$ 1,150.00 x
1	Lh frt fender <i>11</i>	\$ 945.50 x
1	Lh frt fender inner shield <i>11</i>	\$ 185.50 x
1	Lh frt wheel bearing <i>Page</i>	509.10 \$ 543.73 ✓
1	Lh frt knuckle arm <i>Wapet</i>	522.30 \$ 684.64 ✓
1	Lh frt lower arm <i>But</i>	284.90 \$ 386.60 ✓
1	Lh frt shock absorber <i>11 x</i>	\$ 553.02 x
1	Lh frt shock absorber top mounting <i>11 x</i>	\$ 216.26 x
1	Lh wing mirror assy <i>cut / Page</i>	998.35 \$ 1,785.85 ✓
1	Lh rocker panel skirt <i>11 x</i>	\$ 850.00 x
Parts Sum:		\$ 13,448.47
Parts Less 5% :		\$ 672.42
Parts Total:		\$ 12,776.05

Special Nett Items

1	Bumper lower skirt <i>De/wapet</i>	\$ 600.00 500
1	Front bumper clips <i>nei 30</i>	\$ 50.00 30
1	Front bumper rivets <i>nei 30</i>	\$ 50.00 30
1	Lh frt fender inner shield clips <i>11 x</i>	\$ 50.00 x
1	Lh frt rim <i>cut 650</i>	\$ 800.00 650
1	Front number plate <i>11</i>	\$ 50.00 x
Special Nett Items Total:		\$ 1,600.00

Labour & Misc Charges

Description	Amount
To Check Wiring	\$ 50.00 20
To Diagnose/Reset/reprogram	\$ 11 280.00 X
Anti-rust	\$ 11 120.00 X
Replace front undercarriage	\$ 350.00 150
Computerise wheel alignment	\$ 120.00 80
Labour to remove necc parts, cut and reweld panel	\$ 900.00 400
Spray painting	\$ 1,000.00 550
Labour Charges Total:	\$ 2,820.00

Parts Total: \$ 12,776.05
Special Nett Items Total: \$ 1,600.00
Labour Charges Total: \$ 2,820.00
Total Cost Of Repair: \$ 17,196.05
(Non-Inclusive of GST)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5653.75
52
P- 5372.96
S. N- 1210
2 - 1200
7782.96
252
6226.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	915I
Vehicle Details	
Vehicle No.:	SGY564A
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2023
Vehicle Make:	B.M.W.
Vehicle Model:	116I AT ABS D/AIRBAG 2WD HID 5DR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	A056J101N13B16A
Chassis No.:	WBA1A12060E948276
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,470.00
Original Registration Date:	20 Jan 2012
First Registration Date:	20 Jan 2012
Transfer Count:	8
Actual ARF Paid:	\$27,470.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2031
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$50,570.00
COE Rebate Amount:	\$43,038.00
Total Rebate Amount:	\$43,038.00

The information contained herein is correct as at 27 Jun 2023

OK