

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 06 Jul 2023

Preliminary Advice

Vehicle No	: GBG1145Z	Accident Date	: 21/06/2023
Make	: NISSAN NV200	Policy No.	: MCV23B00006900
Assignment Date	: 28/06/2023	Excess	: S\$600.00
Date of Inspection	: 05/07/2023	Est. Duration of Repair	: 4
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 1 DEFU LANE 6 SINGAPORE 539365		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,755.00
Revised Amount	:S\$	2,622.00
Check Items (Estimated)	:S\$	165.00
Total	:S\$	2,787.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	34,000.00
COE / PARF Rebate	:S\$	11,952.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,048.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.