

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23006540/KQY3E2**Date:** 20/07/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002342625
<b>Claimant Vehicle No :</b>	SNK1455R	<b>Insured Vehicle No :</b>	SGQ8687T
Date of Loss:	28/06/2023	Nature of Claim:	TP
		Claim No:	320282

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNK1455R</b>	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 RWD, (A)	Chassis No:	LRW3F7FS0PC799295
Reg. Date:	23/03/2023 (Man. Year: 2023)	Odometer:	5349 km
Colour:	Metallic Pearl White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,209.63	580.37	1,629.26	73.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,100.00	660.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,969.63</b>	<b>1,680.37</b>	<b>2,289.26</b>	<b>57.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	3,969.63	1,300.00	2,669.63	67.25
<b>+ GST 8.00/8.00% (S\$)</b>	317.57	104.00	213.57	67.25
<b>Nett Amount (S\$)</b>	<b>4,287.20</b>	<b>1,404.00</b>	<b>2,883.20</b>	<b>67.25</b>

INSPECTION

Date of Assignment:	30/06/2023	Optima Werkz Pte Ltd (HQ)
Date Inspected:	03/07/2023 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2023)
<b>Parts:</b>	143	TESLA MODEL 3 RWD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNK1455R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	448.60 FL	*448.60 FL
2	1		*FRONT FENDER INNER SHIELD RH	Serviceable	116.82 FL	*- FL
3	1		*FRONT FENDER SIGNAL LAMP WITH CAMERA RH	Cut	196.26 FL	*196.26 FL
4	1		*FRONT DOOR RH	Repair	1,009.35 FL	*- FL
5	1		*FRONT DOOR WEATHERSTRIP RH	Serviceable	88.79 FL	*- FL
6	1		*SIDE SKIRT RH	Serviceable	448.60 FL	*- FL
7	1		*FRONT SIDE MIRROR COVER RH	Serviceable	46.73 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	40.00 FS	*- FS
9	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,445.15</b>	<b>644.86</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	235.52	64.49
<b>Total Parts (\$\$)</b>	<b>2,209.63</b>	<b>580.37</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	700.00	400.00
2	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH	New	120.00	0.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	120.00	20.00
5	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER RH, FRONT DOOR RH, SIDE SKIRT RH	New	700.00	650.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,760.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >