

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 13 Jul 2023

Preliminary Advice

Insured Vehicle No	: SGQ8687T	Accident Date	: 28/06/2023
TP Vehicle No	: SNK1455R	Assignment Date	: 30/06/2023
Make	: TESLA MODEL 3 RWD	Est. Duration of Repair	: 4
Date of Inspection	: 03/07/2023		
Inspection At	: OPTIMA WERKZ PTE LTD (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,969.63
Revised Amount	:S\$	1,680.37
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,680.37
 Lump Sum Repair	 :S\$	 1,300.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	228,000.00
COE / PARF Rebate	:S\$	126,252.00
Salvage Value	:S\$	
Margin for Repair	:S\$	101,748.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.