



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC23006017/Tvy3e2-1	
			Date: 11/07/2023	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 4739R	Veh. Inspected	YM 9900D
	Policy No.		Coverage (\$)	0.00
	Claim No.	23/23/23/VC05/027553	Excess (\$)	0.00
	Assign From	HUEY NI	Assign Date	28/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN MKB37	c.c	7684
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MKB37BN00232	Colour	WHITE
	Odometer	322542 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/90 R17.5	BRIDGESTONE	8 mm
	L/H Front Tyre	225/90 R17.5	BRIDGESTONE	8 mm
	R/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	8/8 mm
	L/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/06/2023	Inspection Date	15/06/2023
	Survey held at	TONG HENG MOTOR WORKS BLK 6 KRANJI ROAD #01-26 . SINGAPORE 739542		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	