

Not Authenticated
Delivery B4 point

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5442P

AAD2306-

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

27 JUN 2023

SHC5442P

JTDKB3FU203092189

200303878K

TOYOTA

PRIUS GEN 4

25/6/2023

SFH73B/TOKIO

15/4/2021

PART

LIST

1	COVER, REAR BUMPER	\$	R ₁	612.68	✓
1	COVER, REAR BUMPER, LOWER	\$	R ₁	27.93	✓
1	GUARD, REAR BUMPER, CENTER	\$	R ₁	472.19	✓
1	SEAL, REAR BUMPER SIDE, LH	\$	R ₁	149.21	✓
1	SEAL, REAR BUMPER SIDE, RH	\$	R ₁	149.21	X
1	RETAINER, REAR BUMPER SIDE, LH	\$	R ₁	167.48	✓
1	REAR BUMPER SIDE RETAINER RH	\$	R ₁	167.48	X
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	R ₁	419.90	✓
1	REFLECTOR ASSY, REFLEX, LH	\$	R ₁	49.25	✓
1	REFLECTOR ASSY, REFLEX, RH	\$	R ₁	49.25	X
1	COVER, REAR COMBINATION LAMP, RH	\$	R ₁	88.41	X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	R ₁	428.19	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	R ₁	329.49	X
1	COVER, REAR COMBINATION LAMP, LH	\$	R ₁	88.41	X
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	R ₁	428.19	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	R ₁	329.49	X
1	COVER, FLOOR UNDER, RH	\$		220.50	?
1	COVER, FLOOR UNDER, LH	\$		304.92	?
1	COVER, REAR FLOOR	\$	R ₁	290.43	✓
1	COVER, DECK TRIM, REAR	\$	R ₁	159.39	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	R ₁	824.46	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	R ₁	1,443.86	✓
1	BOARD, BACK DOOR TRIM	\$	R ₁	284.55	X
1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	R ₁	65.73	X
1	STAY ASSY, BACK DOOR, LH	\$	R ₁	305.66	X
1	STAY ASSY, BACK DOOR, RH	\$	R ₁	305.66	X
1	HINGE ASSY, BACK DOOR, LH	\$	R ₁	77.18	X
1	HINGE ASSY, BACK DOOR, RH	\$	R ₁	77.18	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	R ₁	1,156.89	✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	R ₁	68.88	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5442P

- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

AAD2306-

	\$	<i>na</i>	68.88	—
	\$	<i>na</i>	90.30	—
TOTAL	\$		9,701.23	
25%	\$		2,425.31	
	\$		7,275.92	

SPECIAL NETT**1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

	\$	<i>na</i>	700.00	<i>2201a</i>
	\$	<i>na</i>	65.00	<i>601a</i>
	\$	<i>na</i>	65.00	<i>x</i>
	\$	<i>na</i>	65.00	<i>x</i>
	\$	<i>na</i>	60.00	<i>x</i>
	\$	<i>na</i>	180.00	<i>301a</i>
	\$	<i>na</i>	150.00	<i>801a</i>
	\$	<i>na</i>	200.00	—
	\$	<i>na</i>	130.00	<i>301a</i>
TOTAL	\$		1,615.00	
TOTAL PARTS	\$		8,890.92	

LABOUR

To rust-proofing of the affected areas.

\$ 600.00 *301*

Putty and spray painting of the affected portion.

\$ 1,200.00 *801a*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *601*

To transfer of tailgate fittings and conduct water seepage test.

\$ 170.00 *601*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$ 170.00 ✓

To transfer of tailgate fittings and conduct water seepage test.

\$ *Payson* 170.00 *x*

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHCS442P

AAD2306-

To transfer of bootlid fittings, attachments and perform
water seepage test.

\$ *nn* 170.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

TOTAL \$ 5,250.00

OVERALL TOTAL \$ 14,140.92

5 day