

ASS. REC. BY:

REF:

Tm1/23006556/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: £58,163/1

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/H 5442P

Yr Regn:

04, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pns

C.C

1798

Colour

A.P. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

173092

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31-U 2030 92189

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Wanli

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/6/23

D.O.I.

27/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

417 @ 6851.76 Cdn (Red. # 7289.16, 51%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHC5442P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H01068
Chassis No.:	JTDKB3FU203092189
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	15 Apr 2021
First Registration Date:	15 Apr 2021
Transfer Count:	0
Actual ARF Paid:	\$7,030.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2029
PARF Rebate Amount:	\$5,272.00

Intended COE Rebate Details

COE Expiry Date:	14 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,827.00
COE Rebate Amount:	\$24,534.00
Total Rebate Amount:	\$29,806.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Jun 2023

OK

Not Authorized
Recovery By paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5442P

AAD2306-

Q 6831.76

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

27 JUN 2023

SHC5442P

JTCKB3FU203092189

200303878K

TOYOTA

PRIUS GEN 4

25/6/2023

SFH73B/TOKIO

15/4/2021

PART

LIST

1 COVER, REAR BUMPER	\$	R 612.68	✓
1 COVER, REAR BUMPER, LOWER	\$	M 27.93	✓
1 GUARD, REAR BUMPER, CENTER	\$	R 472.19	✓
1 SEAL, REAR BUMPER SIDE, LH	\$	M 149.21	✓
1 SEAL, REAR BUMPER SIDE, RH	\$	M 149.21	X
1 RETAINER, REAR BUMPER SIDE, LH	\$	M 167.48	✓
1 REAR BUMPER SIDE RETAINER RH	\$	M 167.48	X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	R 419.90	✓
1 REFLECTOR ASSY, REFLEX, LH	\$	M 49.25	✓
1 REFLECTOR ASSY, REFLEX, RH	\$	M 49.25	X
1 COVER, REAR COMBINATION LAMP, RH	\$	M 88.41	X
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$	M 428.19	X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	M 329.49	X
1 COVER, REAR COMBINATION LAMP, LH	\$	M 88.41	X
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$	M 428.19	X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	M 329.49	X
1 COVER, FLOOR UNDER, RH	\$	M 220.50	X
1 COVER, FLOOR UNDER, LH	\$	M 304.92	X
1 COVER, REAR FLOOR	\$	M 290.43	✓
1 COVER, DECK TRIM, REAR	\$	M 159.39	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	R 824.46	✓
1 PANEL SUB-ASSY, BACK DOOR	\$	R 1,443.86	✓
1 BOARD, BACK DOOR TRIM	\$	M 284.55	X
1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	M 65.73	X
1 STAY ASSY, BACK DOOR, LH	\$	M 305.66	X
1 STAY ASSY, BACK DOOR, RH	\$	M 305.66	X
1 HINGE ASSY, BACK DOOR, LH	\$	R 77.18	X
1 HINGE ASSY, BACK DOOR, RH	\$	R 77.18	X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	M 1,156.89	✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	M 68.88	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5442P

AAD2306-

- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	<i>Mr</i>	68.88	—
\$	<i>Mr</i>	90.30	—
TOTAL \$		9,701.23	
25% \$		2,425.31	
\$		7,275.92	

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>Mr</i>	700.00	<i>2200a</i>
\$	<i>Mr</i>	65.00	<i>601a</i>
\$	<i>Mr</i>	65.00	<i>x</i>
\$	<i>Mr</i>	65.00	<i>x</i>
\$	<i>Mr</i>	60.00	<i>x</i>
\$	<i>Mr</i>	180.00	<i>301a</i>
\$	<i>Mr</i>	150.00	<i>801a</i>
\$	<i>Mr</i>	200.00	—
\$	<i>Mr</i>	130.00	<i>301a</i>
TOTAL \$		1,615.00	
TOTAL PARTS \$		8,890.92	

LABOUR

To rust-proofing of the affected areas.	\$	600.00	<i>301</i>
Putty and spray painting of the affected portion.	\$	1,200.00	<i>8801</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	<i>6001</i>
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	<i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>601</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	✓
To transfer of tailgate fittings and conduct water seepage test.	\$	<i>Revised</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5442P**AA02306-**To transfer of bootlid fittings, attachments and perform
water seepage test.\$ *nn* 170.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X***TOTAL** \$ 5,250.00**OVERALL TOTAL** \$ 14,140.92*5 days*