

Not Authorized
Resurvey BQ print

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHF620J

AAD2306-105

Vehicle No.:
Chassis No.:
Co UEN.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

27 JUN 2023

SHF620J
JTDKB3FUX03093588
200303878K
TOYOTA
PRIUS GEN 4
26/6/2023
SMN7056R/TOKIO
28/1/2021

PART

LIST

- 1 COVER, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 CAP, WHEEL
- 1 RIM

\$	K B	612.68	X
\$	P B	472.19	X
\$	P	49.25	X
\$	P	149.21	X
\$	P	167.48	X
\$	P	220.50	X
\$	P	290.43	X
\$	P	159.39	X
\$	K B	824.46	X
\$	P	428.19	X
\$	P	329.49	X
\$	P	88.41	X
\$	K	1,099.46	X
\$	P	176.09	X
\$	P	266.91	X
\$	P	1,995.11	X

TOTAL \$ 7,329.25
25% \$ 1,832.31
\$ 5,496.94

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING

\$	P	700.00	X
\$	na	65.00	
\$	na	65.00	
\$	na	65.00	
\$	na	60.00	
\$	na	180.00	
\$	na	150.00	
\$	na	200.00	

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
SHF620J

AAD2306-105

1 WINDSCREEN INNER SPONGE SEAL

	\$	nn	130.00	X
TOTAL	\$		1,615.00	
TOTAL PARTS	\$		7,111.94	

LABOUR

To rust-proofing of the affected areas.

\$ nn 600.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 22d

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 8d

To transfer of tailgate fittings and conduct water seepage test.

\$ nn 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ L 380.00 X

To transfer of tailgate fittings and conduct water seepage test.

\$ L 170.00 X

To reinstall rear bumper parking sensor.

\$ L 170.00 X

To check steering geometry and computer wheel alignment

\$ L 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ L 170.00 X

TOTAL \$ 5,080.00**OVERALL TOTAL \$ 12,191.94**

1 day