

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0236/23

DATE : 26-JUN-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

S(068897)

TEL : 63954779/67143369

FAX : 63953768

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : PRIMAC ENGINEERING P L - GIVEN 3 FREE SVC BY T8 EK

ADDRESS : 10 ANSON ROAD

#05-17

INTERNATIONAL PLAZA S(079903)

TELEPHONE NO : -

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 7210055420-02

VEHICLE NO : GBD8255J

MODEL CODE : NV200 DX 1.6 A

MODEL/YEAR : NV200

ENGINE NO : HR16027482D

CHASSIS NO : VM20078574

MILEAGE : 141632 KM

DATE IN : 26/06/2023

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 26/06/2023

- 9645 0084 elmer@tanchoq.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjun 97495749/62563561

3/7/23 @ 10am

8 days

Resurvey before paint

Tanjun @ lkkauto.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBD8255J

| S/NO | JOB CODE | NATURE OF JOB | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|--|-------------------|---------------------------|
| 1 | ZZ/001 | LABOR CHARGES TO REPAIR BOTH RR FENDER, TRUNK FLOOR INNER RR END PANEL, RENEW TAIL GATE, RR BUMP AND | 2340.00 | 1950- |
| 2 | ZZ/002 | OUTER RR END PANEL | | |
| 3 | ZZ/003 | CHARGES TO SPRAY PAINTING SAME | 1250.00 | 1000. |
| 4 | ZZ/004 | REMOVE AND INSTALL REAR WINDSCREEN GLASS | 190.00 | ✓ |
| 5 | ZZ/005 | REMOVE/INSTALL BOTH RR COMB LAMP /REPLACE IF DAMGE | 80.00 | ✓ |
| 6 | ZZ/006 | APPLY SEALANT TO TAIL GATE AND REAR END PANEL OUTER @SGD\$100.00 EACH | 200.00 | ✓ |
| 7 | ZZ/007 | REMOVE AND TRANSFER TAIL GATE MECHANISM | 80.00 | ✓ |
| 8 | ZZ/008 | RENEW REVERSE SENSOR | 110.00 | ✓ |
| 9 | ZZ/009 | COMPUTER CHECK DIAGNOSIS | 120.00 | ✓ |
| TOTAL LABOUR CHARGES | | | 4370.00 | |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD8255J

| S/NO | PARTS DESCRIPTION | PARTS NUMBER | DAMAGED PARTS & PRICES | | |
|------|---------------------------------|--------------|------------------------|------|--------------|
| | | | NETT | LIST | S/NETT REMAR |
| 1 | CENTER FINISHER TAIL GATE | 90810-JX30A | 391.80 | de | |
| 2 | LH RR COMB LAMP | 26555-JX53A | 280.60 | ? | |
| 3 | RH RR COMB LAMP | 26550-JX00A | 280.60 | ? | |
| 4 | EMBLEM-REAR VANNETTE | 90892-JX00A | 72.20 | new | |
| 5 | EMBLEM-REAR NV200 | 90895-JX00A | 105.00 | new | |
| 6 | EMBLEM-REAR NISSAN | 90890-JX00A | 72.20 | de | |
| 7 | SENSOR-REVERSE | SENSOR | | | 250.00 new |
| 8 | REAR LICENCE PLATE | RLP | | | 60.00 bb |
| 9 | INNER RR END PANEL | 75614-JX00A | 641.30 | de ? | } plus |
| 10 | OUTER RR END PANEL | 75617-JX00A | 128.30 | ? | |
| 11 | 70KM/H | 70KM/H | | | 15.00 new |
| 12 | LABEL-PAX6 | PAX | | | 15.00 new |
| 13 | LH STAY TAIL GATE | 90451-JX00A | 222.70 | X | |
| 14 | RH STAY TAIL GATE | 90450-JX00A | 222.70 | X | |
| 15 | SUNDRIES | NPN | | | 50.00 |
| 16 | REAR W/SCREEN SEALANT | SEALANT - 4 | | | 80.00 new |
| 17 | WEATHER STRIP TAIL GATE | 90830-5LA0A | 98.40 | ? | |
| 18 | TAIL GATE | K010M-JX00B | 1819.60 | bb | |
| 19 | TOW HOOK COVER RR BUMPER | 85010-JX00A | 15.70 | ? | |
| 20 | RH SIDE BRACKET RR BUMPER | 85228-JX00A | 41.50 | ? | |
| 21 | LH SIDE BRACKET RR BUMPER | 85229-JX00A | 41.50 | ? | |
| 22 | ENERGY ABSORBER RR BUMPER | 85090-JX00A | 104.70 | ? | |
| 23 | CLIP RR BUMPER @ SGD\$1.50 EACH | 01553-05933 | 15.00 | new | |
| 24 | REAR BUMPER | 85022-5LA0B | 1020.40 | de | |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD8255J

DAMAGED PARTS & PRICES

| S/NO PARTS DESCRIPTION | PARTS NUMBER | NETT | LIST | S/NETT REMAR |
|---|--------------|---------|------|--------------|
| SUB TOTAL | | 5574.20 | 0.00 | 470.00 |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) | | 1114.84 | 0.00 | 0.00 |
| GRAND TOTAL | | 4459.36 | 0.00 | 470.00 |
| OVERALL TOTAL | | 4929.36 | | |

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBD8255J

TOTAL LABOUR CHARGES 4370.00
TOTAL SPARE PARTS CHARGES 4929.36

GRAND TOTAL 9299.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.