

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
03-07-2023
5211052769
201903913C
30001
2023017397/ 1
28-06-2023
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SNK4154P	NS74QZS0	12-04-2023	TMBME7NS5N8500136	Kodiaq FL Style 2.0 TSI 140kW DSG	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNES				#6	280.00	302.40
	REPAIR						
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
9801B001	TO ALIGN LED HEADLIGHT				#6	100.00	108.00
565807217	Unbekannt	1	pcs.	2,208.62	10.00%	1,987.76	2,146.78
	FRT BUMPER				#6		
565919493D GRU	Unbekannt	1	pcs.	25.94	10.00%	23.35	25.22
	SENSOR BRACKET				#6		
565919494D GRU	Unbekannt	1	pcs.	25.94	10.00%	23.35	25.22
	SENSOR BRACKET				#6		
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	10.00%	76.18	82.27
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	10.00%	66.93	72.28
565807061C 9B9	Unbekannt	1	pcs.	441.02	10.00%	396.92	428.67
	BUMPER SPOILER				#6		
565807812	Unbekannt	1	pcs.	82.39	10.00%	74.15	80.08
	FRT BUMPER INNER AIR DUCT RH				#6		
565807050	Guide Plec	1	pcs.	68.38	10.00%	61.54	66.46
	BUMPER SIDE BRACKET RH				#6		
565807368C 9B9	Unbekannt	1	pcs.	58.99	10.00%	53.09	57.34
	RHS BUMPER LOWER GRILLE				#6		
567941036	Unbekannt	1	pcs.	4,197.32	10.00%	3,777.59	4,079.80
	RHS H/LAMP				#6		
565821106	Fender	1	pcs.	1,070.14	10.00%	963.13	1,040.18
	RHS FENDER				#6		
565821142	Fender - B	1	pcs.	63.81	10.00%	57.43	62.02
	RHS FENDER BRACKET				#6		
565809958E	Unbekannt	1	pcs.	347.84	10.00%	313.06	338.10
	RHS FENDER LINER				#6		
565854732A 9B9	Unbekannt	1	pcs.	276.56	10.00%	248.90	268.81
	RHS FENDER WHEEL ARCH				#6		
	LABOUR				#6		
	SPRAY PAINT	12	pcs.	720.00		2,880.00	3,110.40
	ALLIANZ DIRECT	12	pcs.	680.00		2,720.00	2,937.60
	DOA: 26/06/2023						
	TP VEH: SLD3959B						
	SURVEY BY:						

Quotation valid till 05-07-2023

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#6	860.00	13,723.38	902.58	8%	1,166.67	902.58	14,583.38	15,750.05
Total	860.00	13,723.38	902.58		1,166.67	902.58	14,583.38	15,750.05

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

03-07-2023
5211052769
201903913C
30001
2023017397/ 1
28-06-2023
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SNK4154P	NS74QZS0	12-04-2023	TMBME7NS5N8500136	Kodiaq FL Style 2.0 TSI 140kW DSG	20

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 92010068
5 days
03/07/23 @ 1020
Resurvey by paint