



1

of 2 ?

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 SINGAPORE 068897

Ref: CS3/AIS23006627/Rnp3

Date: 03/07/2023

Code: AIS

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJK 153R	Veh. Inspected	SNJ 6503H
Policy No.		Coverage (\$)	0.00
Claim No.	2023 32009997	Excess (\$)	0.00
Assign From		Assign Date	01/07/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/06/2023	Inspection Date	03/07/2023
Survey held at	BMW MOTORWORKSHOP BLK 1009 BUKIT MERAH LANE 3 #01-86 SINGAPORE 159723		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--