

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
HEADLAMP LH		1	4086.22	-30.00 %	2,860.35
FRONT BUMPER		1	881.30	-30.00 %	616.91
FRONT BUMPER FOGLAMP LH		1	345.00	-30.00 %	241.50
FRONT BUMPER FOGLAMP GARNISH LH		1	145.50	-30.00 %	101.85
FRONT BUMPER CHROME MOULDING LH		1	224.10	-30.00 %	156.87
FRONT BUMPER SIDE RETAINER LH		1	127.20	-30.00 %	89.04
FRONT FENDER LH		1	1264.20	-30.00 %	884.94
FRONT FENDER EMBLEM LH		1	137.40	-30.00 %	96.18
FRONT FENDER INNER SHIELD		1	276.20	-30.00 %	193.34
FRONT WHEEL RIM LH		1	650.00	-30.00 %	455.00
FRONT WHEEL BEARING LH		1	282.30	-30.00 %	197.61
FRONT KNUCKLE LH		1	796.80	-30.00 %	557.76
FRONT SHOCK ABSORBER LH		1	598.80	-30.00 %	419.16
FRONT LOWER ARM LH		1	1443.20	-30.00 %	1,010.24

Parts Subtotal 7,880.75

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER CLIPS		1.0	60.00	0.00 %	60.00
FRONT FENDER INNER SHIELD CLIP		1.0	60.00	0.00 %	60.00
FRONT TYRE LH		1.0	280.00	0.00 %	280.00

Materials Subtotal 400.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO CHECK WIRING	RnR	50.00	0.00 %	50.00

REFOCUS HEADLAMP	RnR	120.00	0.00 %	120.00
RNR UNDERCARRIAGE DAMAGES PART	RnR	280.00	0.00 %	280.00
WHEEL ALIGNMENT	RnR	80.00	0.00 %	80.00
LABOUR CHARGE	RnR	600.00	0.00 %	600.00
REPLACE TYRE AND BALANCING	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	600.00	0.00 %	600.00
General Labor Subtotal				1,210.00
Paint Labor Subtotal				600.00
Labor Subtotal				1,810.00

Summary

Repair Cost	10,090.75
Discount(0 %)	(0.00)
	10,090.75
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	10,090.75