

TECHWERKZ AUTOMOTIVE PTE LTD

UEN: 202308089K

27 Pasir Ris St 72 #04-16 Whitewater Singapore 518767

Tel.: +65 9105 7898 Email: bernardteo@techwerkzautomotive.com

TP SMRT.

Xiao Chen.

2WR800278200

Vehicle No: SLV5146Y

Model: Toyota Voxy

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
HEADLAMP LH <i>nt</i>		1	4086.22 3606.	-30.00 %	2,860.35 ✓
FRONT BUMPER <i>Del'd</i>		1	881.30	-30.00 %	616.91 ✓
FRONT BUMPER <i>ren</i>		1	345.00	-30.00 %	241.50 +
FOGLAMP LH					
FRONT BUMPER <i>64 ren</i>		1	145.50	-30.00 %	101.85 +
FOGLAMP GARNISH LH					
FRONT BUMPER <i>nt</i>		1	224.10	-30.00 %	156.87 ✓
CHROME MOULDING LH					
FRONT BUMPER SIDE <i>ren</i>		1	127.20	-30.00 %	89.04 +
RETAINER LH					
FRONT FENDER LH <i>Del'd</i>		1	1264.20 906.	-30.00 %	884.94 ✓
FRONT FENDER <i>ren</i>		1	137.40	-30.00 %	96.18 ✓
EMBLEM LH					
FRONT FENDER <i>ren</i>		1	276.20	-30.00 %	193.34 +
INNER SHIELD					
FRONT WHEEL RIM <i>nt</i>		1	650.00	-30.00 %	455.00 ✓
LH					
FRONT WHEEL BEARING LH		1	282.30	-30.00 %	197.61 +
FRONT KNUCKLE LH		1	796.80	-30.00 %	557.76 +
FRONT SHOCK ABSORBER LH		1	598.80	-30.00 %	419.16 +
FRONT LOWER ARM LH		1	1443.20	-30.00 %	1,010.24 +
Parts Subtotal					7,880.75

25%.

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER CLIPS <i>ren</i>		1.0	60.00	0.00 %	60.00 30
FRONT FENDER INNER SHIELD CLIP <i>ren</i>		1.0	60.00	0.00 %	60.00 +
FRONT TYRE LH <i>ren</i>		1.0	280.00	0.00 %	280.00 +
Materials Subtotal					400.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO CHECK WIRING	RnR	50.00	0.00 %	50.00 30

REFOCUS HEADLAMP	RnR	120.00	0.00 %	120.00	X
RNR UNDERCARRIAGE DAMAGES PART	RnR	280.00	0.00 %	280.00	X
WHEEL ALIGNMENT	RnR	80.00	0.00 %	80.00	✓
LABOUR CHARGE	RnR	600.00	0.00 %	600.00	500
REPLACE TYRE AND BALANCING	RnR	80.00	0.00 %	80.00	X

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	600.00	0.00 %	600.00 400
General Labor Subtotal				1,210.00
Paint Labor Subtotal				600.00
Labor Subtotal				1,810.00

Summary

Repair Cost	10,090.75
Discount(0 %)	(0.00)
	10,090.75
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	10,090.75

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C.

1/s 03/07/23.

0.5 days.

Total: 5,843.60

1/s: 4650