

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI23006639/DNY3Q2  
**Date:** 18/07/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000815
<b>Claimant Vehicle No :</b>	SHA3811G	<b>Insured Vehicle No :</b>	SNG3045Z
Date of Loss:	29/06/2023	Nature of Claim:	TP
		Claim No:	M2303789

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA3811G</b>	Engine No:	2ZRR962379
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU503537475
Reg. Date:	18/11/2016 (Man. Year: 2016)	Odometer:	778002 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,970.78	1,437.81	1,532.97	51.60
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,970.00	1,300.00	670.00	34.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,951.78</b>	<b>2,748.81</b>	<b>2,202.97</b>	<b>44.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>(S\$)</b>	4,951.78	2,200.00	2,751.78	55.57
<b>+ GST 8.00/8.00% (S\$)</b>	396.14	176.00	220.14	55.57
<b>Nett Amount (S\$)</b>	<b>5,347.92</b>	<b>2,376.00</b>	<b>2,971.92</b>	<b>55.57</b>

**INSPECTION**

Date of Assignment:	03/07/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/06/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

**Adjuster:** BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2023)
<b>Parts:</b> 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHA3811G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RAER BUMPER	Mtg Broken	503.04 FL	*503.04 FL
2	1		*RAER BUMPER BRACKET RH	Not Necessary	112.70 FL	*- FL
3	1		*RAER BUMPER LOWER MOULDING	Not Necessary	654.96 FL	*- FL
4	10		*RAER BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
5	1		*RAER BUMPER SIDE LOWER COVER RH	Serviceable	148.40 FL	*- FL
6	1		*RAER FENDER RH	Dented	992.04 FL	*992.04 FL
7	1		*TAIL LAMP UPPER RH	Not Necessary	557.90 FL	*- FL
8	1		*TAIL LAMP LOWER RH	Not Necessary	570.00 FL	*- FL
9	2		*REAR FENDER ADVERTISEMENT	Necessary	200.00 FS	*200.00 FS
10	1		*REAR BUMPER ADVERTISEMENT	Necessary	50.00 FS	*50.00 FS
11	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,861.04</b>	<b>1,817.08</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	890.26	379.27
<b>Total Parts (\$)</b>	<b>2,970.78</b>	<b>1,437.81</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
			<b>Sub Total (\$\$)</b>	<b>11.00</b>
				<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,100.00	700.00
2	SPRAY PAINTING	New	600.00	500.00
3	REMOVE/REFIX REAR UPHOLSTERY	New	120.00	80.00
4	CHECK LIGHTING AND WIRING	New	60.00	0.00
5	TUFF COATING	New	90.00	20.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,970.00</b>
				<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >