

ABS. P.C. BY:

REF:

CS | TMI 23006639 | Dmy 3

ASSIGNMENT

COB. NOV 2024
Yr Regn: Nov 2016

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

DAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 8THA 3811 G

Type: MLCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prins c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 778002 T/Radio: Insured / Std / NI / NA

Eng/No: 22R R962379

C/No: JTDKB3FU503537475

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15
R: _____

BS / DUN / EXIOVA / GY / FS / LZA / MIC / OHSU / PIR / SUMI /
TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 29/06/2023 D.O.I. 30/06/2023

Survey held at CDGB Kwang

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
0/3 R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Tokio SNG 20457
12/7/23	Invoice 2/5 2,200/- with 4 days of rep. (Red. \$ 2751.78, 55%)

Date/Time, File Pass to?

: Prel. Report
 : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)

Survey Fee:	
Transportation:	
S + RS \$	
Photos	
Others	

Report Format: _____

Union Form 11 D to 12

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/06/2023
Vehicle Reg. No.:	SHA3811G	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	18/11/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRR9623792	Chassis No:	JTDKB3FU503537475
Odometer:	778002 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,970.78
Miscellaneous Items	11.00
Labour	1,970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,951.78
+ GST 8.00% (S\$)	396.14
Nett Amount (S\$)	5,347.92

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 30 Jun 2023)
Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA3811G/30/06/2023 13:46
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RAER BUMPER <i>mounty broken</i>	25.00	0.00	*503.04 FL ✓
2	1		*RAER BUMPER BRACKET RH <i>✓ HH</i>	25.00	0.00	*112.70 FL ✓ X
3	1		*RAER BUMPER LOWER MOULDING <i>HH</i>	25.00	0.00	*654.96 FL X
4	10		*RAER BUMPER CLIP <i>HCC</i>	25.00	0.00	*22.00 FL ✓
5	1		*RAER BUMPER SIDE LOWER COVER RH <i>SC</i>	25.00	0.00	*148.40 FL X
6	1		*RAER FENDER RH <i>Dark</i>	25.00	0.00	*992.04 FL ✓
7	1		*TAIL LAMP UPPER RH <i>HH</i>	25.00	0.00	*557.90 FL X
8	1		*TAIL LAMP LOWER RH <i>HH</i>	25.00	0.00	*570.00 FL X
9	2		*REAR FENDER ADVERTISEMENT <i>HCC</i>	0	0.00	*200.00 FS ✓
10	1		*REAR BUMPER ADVERTISEMENT <i>HCC</i>	0	0.00	*50.00 FS ✓
11	1		*REAR BUMPER MAT <i>HCC</i>	0	0.00	*50.00 FS ✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,861.04
- List Item Discount on L Items (\$)	890.26
Total Parts (\$)	2,970.78

ComfortDelGro Engineering Pte Ltd/SHA3811G/30/06/2023 13:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

SN 300.00

List 1517.08

25% 1137.81

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer) <i>Hu</i>	11.00 ✓
		<i>11.00 =</i>	
		Sub Total (\$\$)	11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,100.00 <i>700/-</i>
2	SPRAY PAINTING	New	600.00 <i>500/-</i>
3	REMOVE/REFIX REAR UPHOLSTERY	New	120.00 <i>80/-</i>
4	CHECK LIGHTING AND WIRING	New	60.00 <i>Hu</i>
5	TUFF COATING	New	90.00 <i>20/-</i>
		<i>1300.00 =</i>	
		Gross Labour Cost (\$\$)	1,970.00

ComfortDelGro Engineering Pte Ltd/SHA3811G/30/06/2023 13:46. Not valid without Reference section.
 Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

30/06/2023 @ 1700m
N/A Actual
2/5m
4 days.
2Kk sub


2748.81
4/s 2200/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: