

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Foo Ai Ngoh

Date: 07 Jul 2023

**Preliminary Advice**

Vehicle No	: GBM782J	Accident Date	: 01/06/2023
Make	: DFSK EC35	Policy No.	: DMCG22014776
Assignment Date	: 30/06/2023	Excess	: S\$2,500.00
Date of Inspection	: 04/07/2023	Est. Duration of Repair	: 14
Inspection At	: HONG SEH MOTORS PTE LTD (LOK YANG ROAD) 10 FOURTH LOK YANG ROAD, JURONG TOWN SINGAPORE 629707		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	52,604.75
Revised Amount	:S\$	18,517.73
Check Items (Estimated)	:S\$	27,242.75
Total	:S\$	45,760.48

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	29,119.00
Salvage Value	:S\$	
Margin for Repair	:S\$	80,881.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.