

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0616/2023/EQ
DATE : 4-Jul-23
WIP : 27087

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/7/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MOHAMED KHAIRUL ANWAR BIN MOHAMED ABDUL ALIM
ADDRESS : 519 PASIR RIS STREET 52
#09-29
SINGAPORE 510519
TELEPHONE : HP +65 94368700
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220140362
VEHICLE NO : **SNJ 1019 Y**
MODEL CODE : AUDI A3 SPORTBACK 1.0 TFS
MODEL YEAR : 22/12/2022
ENGINE NO : DLA E19088
CHASSIS NO : WAUZZZGY7NA099542
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Jun-23
PLACE OF ACCIDENT : SLIP ROAD FROM SG TENGAH ROAD TO KJE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNJ 1019 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,400.00	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	
6	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$	3,000.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 11,522.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 1019 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,778.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 307.00	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 274.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 458.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 281.00	
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 71.00	
7	FRONT BUMPER SPOILER	1	\$ 345.00	
8	FRONT BUMPER TRIM COVER - LH	1	\$ 110.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 181.00	
10	FRONT DUMMY COVER - LH	1	\$ 39.00	
11	RADIATOR GRILLE	1	\$ 1,167.00	
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER	1	\$ 223.00	
13	HORN LOW TONE - LH	1	\$ 157.00	
14	HORN BRACKET	2	\$ 54.00	
15	HORN BRACKET - LH	2	\$ 75.00	
16	FRONT FENDER - LH	1	\$ 1,313.00	
17	FRONT FENDER RIVET	3	\$ 12.00	
18	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 34.00	
19	FRONT FENDER BRACE - LH	1	\$ 104.00	
20	FRONT FENDER BRACKET - LH	1	\$ 49.00	
SUB TOTAL SPARE PARTS		:	\$ 7,032.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 1019 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET	1	\$ 3,330.00	
22	BONNET ATTACHMENT PARTS	1	\$ 269.00	
23	BONNET IMPACT PROTECTION	1	\$ 32.00	
24	BONNET ENGINE SOUND ABSORBER	1	\$ 223.00	
25	BONNET RELEASE ELEMENT	1	\$ 69.00	
26	BONNET RELEASE LEVER	1	\$ 16.00	
27	BONNET BOWDEN CABLE - CENTER	1	\$ 66.00	
28	BONNET RELEASE CABLE COVER	1	\$ 12.00	
29	BONNET LOCK - LH / RH	2	\$ 481.00	
30	BONNET STRIKER - LH / RH	2	\$ 260.00	
31	HEADLIGHT - LH	1	\$ 4,323.00	
32	LIFT CYLINDER - LH	1	\$ 223.00	
33	LIFT CYLINDER HOSE	1	\$ 112.00	
34	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	
35	A/C CONDENSER WITH FLUID RESERVOIR	1	\$ 586.00	
36	LOCK CARRIER	1	\$ 1,030.00	
37	READY-MIX COOLANT	6	\$ 326.00	
38	RADIATOR AIR GUIDE - UPPER	1	\$ 53.00	
39	RADIATOR AIR GUIDE - LH / RH UPPER	2	\$ 68.00	
40	RADIATOR AIR GUIDE - UPPER FRONT	1	\$ 34.00	
SUB TOTAL SPARE PARTS		:	\$ 11,535.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 1019 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE - LH LOWER	1	\$ 34.00	
42	RADIATOR AIR GUIDE - LOWER REAR	1	\$ 45.00	
43	FRONT BUMPER FOAM FILLER PIECE	1	\$ 127.00	
44	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 793.00	
45	FRONT BUMPER GUIDE SECTION - LH	1	\$ 57.00	
46	FRONT BUMPER TOP COVER	1	\$ 94.00	
47	CAUTION SIGN STICKER	1	\$ 17.00	
48	OIL COMPLY WITH VW STANDARD STICKER	1	\$ 14.00	
49	AIR CONDITIONER STICKER	1	\$ 9.00	
50	FRONT NUMBER PLATE	S/N	\$ 60.00	
51	SUNDRIES		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 20,517.00	
TOTAL LABOUR CHARGES		:	\$ 11,522.00	
GRAND TOTAL		:	\$ 32,039.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT