



# PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers  
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779  
Tel: 62934822 Fax: 62963283  
E-mail: admin@priorityservices.sg

Date: 9 December 2021

Your Ref: CMTD2000801/RUC

Our Ref: TP-0031/12/21

Motor Claims Department  
M/s. Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place #03-03  
Singapore Land Tower  
Singapore 048623

**Attention: Ms. Ruth Chua**

Madam,

Inspection of 2018 Yamaha Aerox Scooter  
Registration No.: FC 9119 X  
Odometer Reading: 36666 km (At the time of inspection)  
Chassis No.: MH3SG4640JJ044441

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 18-03-2020, followed by inspection of dismantled parts on 10-11-2020 and resurvey after repairs on 12-11-2020.

The following documents were received: -

- 1) Copy of survey report by M/s. Advanced Automotive Consultancy Pte Ltd
- 2) 44 copies of photos depicting damages sustained by FC 9119 X
- 3) Accident and police reports by riders of FC 9119 X and FBQ 7319 Y
- 4) 5 copies of coloured photos showing the condition of FBQ 7319 Y

The vehicle sustained RH side and LH side damages during an accident on 07-02-2020.

Repair cost submitted was \$3,200.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
2pcs.	Yamaha front suspension – not affected/respray	\$ 600.00	\$ -
1pc.	Yamaha under bracket – not affected	200.00	-
1pc.	Yamaha steering bearing – not necessary/not affected	110.00	-
1pc.	Yamaha front rim – not affected/refitted	360.00	-

2pcs.	Yamaha front wheel bearing – not necessary/not affected	\$ 70.00	\$ -
2pcs.	Yamaha front wheel seal – not necessary/not affected	30.00	-
1pc.	Yamaha exhaust cover	60.00	60.00
1pc.	Yamaha fairing set (colored) – cut	550.00	550.00
1pc.	Yamaha floor board-right (matte black)	60.00	60.00
1pc.	Yamaha side belly pan-right (matte black) – refitted	75.00	-
1pc.	Yamaha floorboard rubber – not necessary/not affected	65.00	-
1pc.	Yamaha front windshield	50.00	50.00
1pc.	Yamaha front windshield bracket – not affected	50.00	-
1pc.	Yamaha pillion foot rest-right – not affected	45.00	-
1pc.	Yamaha pillion foot rest mole/cover-right (matte black) – not affected	55.00	-
		=====	=====
		\$ 2,380.00	\$ 720.00
	Less 10%	238.00	72.00
		=====	=====
		\$ 2,142.00	\$ 648.00

Special Nett Items:-

1pc.	Front number plate – necessary	\$ 15.00	\$ 15.00
1pc.	IU – not affected	175.00	-
1pc.	IU bracket – not necessary/not affected	25.00	-
1pc.	IU decal (sticker) – not necessary	20.00	-
1pc.	Givi rear box – refitted	380.00	-
1pc.	Givi rear box base plate – not necessary/not affected	85.00	-
		=====	=====
	Total For Parts:-	\$ 2,842.00	\$ 663.00
		=====	=====

Labour Charges:-

To remove, reinstall and adjust front rim, front wheel bearing, axle shaft, triple clamps, front fork, steering cone, front brake disc.	\$ 180.00	\$ 100.00
To remove and replace above body damaged parts, check wiring and lighting system.	400.00	200.00
To conduct chassis alignment.	350.00	-
	=====	=====
Total:-	\$ 3,772.00	\$ 963.00
	=====	=====

Lump-sum repairs: \$ 3,200.00 \$ 750.00

Estimated period of repairs: 3 working days

Pre-accident Market Value : About \$ 8,000.00 (At the time of accident)  
COE rebate : \$ 4,640.00 (COE expiry on 12-08-2028)

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

**PRIORITY SERVICES**

A handwritten signature in black ink, appearing to read 'JIMMY S. T. LEE', with a long horizontal flourish extending to the right.

**JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA**  
**Motor Appraiser**

**Surveyed by:**

A handwritten signature in blue ink, appearing to read 'LAWRENCE NG', with a large circular flourish on the left side.

**LAWRENCE NG, MSAAA**  
**Motor Appraiser**