

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003070547-01	Date of Loss:	24/06/2023
Vehicle Reg. No.:	SLF8760M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YIU ZHEN YE		
Driver:	YIU ZHEN YE		

Make/Model:	CHEVROLET SONIC, 1.4 HB 2WD (A)	Vehicle Reg. Date:	14/09/2016
Vehicle Colour:	SILVER		
Engine No:	A14XER151800040	Chassis No:	KL1TA69FJGB512980
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	5

Present Location: **ACCORD AUTO SERVICES PTE LTD (HQ)****COST OF CLAIMS**

	Amount
Parts	6,494.40
Miscellaneous Items	2,240.00
Labour	150.00
Paintwork Labour	0.00
Towing	0.00
	Gross Total (\$)
	8,884.40
	+ GST 8.00% (\$)
	710.75
	Nett Amount (\$)
	9,595.15

This claim is handled by: GOH JACQUELINEGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Jul 2023)**Parts:** 144 CHEVROLET SONIC 1.4 HB 2WD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** **Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28****Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	*1,500.00 F
2	1		*FRONT BONNET HINGE RH	0.00	0.00	*40.00 F
3	1		*FRONT BONNET HINGE LH	0.00	0.00	*40.00 F
4	1		*FRONT BONNET LOCK	0.00	0.00	*107.00 F
5	1		*FRONT BONNET SEAL	0.00	0.00	*17.00 F
6	1		*FRONT BONNET STOPPER	0.00	0.00	*3.00 F
7	1		*FRONT BONNET INSULATOR	0.00	0.00	*110.00 F
8	1		*FRONT HEADLAMP LH	0.00	0.00	*850.00 F
9	1		*FRONT HEADLAMP RH	0.00	0.00	*850.00 F
10	1		*FRONT GRILLE ASSY	0.00	0.00	*290.00 F
11	1		*FRONT EMBLEM	0.00	0.00	*100.00 F
12	1		*FRONT BUMPER	0.00	0.00	*930.00 F
13	1		*FRONT BUMPER SIDE RETINER RH	0.00	0.00	*10.00 F
14	1		*FRONT BUMPER SIDE RETINER LH	0.00	0.00	*10.00 F
15	1		*TOWING COVER	0.00	0.00	*17.00 F
16	1		*FRONT LH FOGLAMP	0.00	0.00	*290.00 F
17	1		*FRONT LH FOGLAMP GARNISH	0.00	0.00	*37.00 F
18	1		*FRONT RH FOGLAMP	0.00	0.00	*290.00 F
19	1		*FRONT RH FOGLAMP GARNISH	0.00	0.00	*37.00 F
20	1		*FRONT REINFORCEMENT BAR	0.00	0.00	*320.00 F
21	1		*SUPPORT PANEL	0.00	0.00	*56.00 F

F=Franchise part.

Sub Total (\$)	5,904.00
+ Margin on L,N Items 10.00% (\$)	590.40
Total Parts (\$)	6,494.40

Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	1,000.00
2	1	SPRAY PAINT ON ALL AFFECTED AREA	1,000.00
3	1	TO APPLY ANTI RUST TREATMENT	120.00
4	1	TO CHECK WIRING SYSTEM	120.00
Sub Total (S\$)			2,240.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	FRONT NUMBER PLATE WITH FRAME	New	45.00
2	FRONT BUMPER CLIPS	New	35.00
3	FRONT LH & RH FENDER INNER SHIELD CLIPS	New	70.00
Gross Labour Cost (S\$)			150.00

Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >