

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003070547-01	Date of Loss:	24/06/2023
Vehicle Reg. No.:	SLF8760M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YIU ZHEN YE		
Driver:	YIU ZHEN YE		

Make/Model:	CHEVROLET SONIC, 1.4 HB 2WD (A)	Vehicle Reg. Date:	14/09/2016
Vehicle Colour:	SILVER		
Engine No:	A14XER151800040	Chassis No:	KL1TA69FJGB512980
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair
(day)

NO
5

Present Location: **ACCORD AUTO SERVICES PTE LTD (HQ)****COST OF CLAIMS**

	Amount
Parts	6,494.40
Miscellaneous Items	2,240.00
Labour	150.00
Paintwork Labour	0.00
Towing	0.00
	Gross Total (S\$) 8,884.40
	+ GST 8.00% (S\$) 710.75
	Nett Amount (S\$) 9,595.15

This claim is handled by: **GOH JACQUELINE**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Jul 2023)
Parts: 144 CHEVROLET SONIC 1.4 HB 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: **Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28**
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	*1,500.00 F BUC
2	1		*FRONT BONNET HINGE RH	0.00	0.00	*40.00 F DOWN
3	1		*FRONT BONNET HINGE LH	0.00	0.00	*40.00 F ?
4	1		*FRONT BONNET LOCK	0.00	0.00	*107.00 F ?
5	1		*FRONT BONNET SEAL	0.00	0.00	*17.00 F ?
6	1		*FRONT BONNET STOPPER	0.00	0.00	*3.00 F ?
7	1		*FRONT BONNET INSULATOR	0.00	0.00	*110.00 F XNN
8	1		*FRONT HEADLAMP LH	0.00	0.00	*850.00 F CRA
9	1		*FRONT HEADLAMP RH	0.00	0.00	*850.00 F XNN
10	1		*FRONT GRILLE ASSY	0.00	0.00	*290.00 F ?
11	1		*FRONT EMBLEM	0.00	0.00	*100.00 F ?
12	1		*FRONT BUMPER	0.00	0.00	*930.00 F DD
13	1		*FRONT BUMPER SIDE RETINER RH	0.00	0.00	*10.00 F XNN
14	1		*FRONT BUMPER SIDE RETINER LH	0.00	0.00	*10.00 F ?
15	1		*TOWING COVER	0.00	0.00	*17.00 F XNN
16	1		*FRONT LH FOGLAMP	0.00	0.00	*290.00 F XNN
17	1		*FRONT LH FOGLAMP GARNISH	0.00	0.00	*37.00 F XNN
18	1		*FRONT RH FOGLAMP	0.00	0.00	*290.00 F XNN
19	1		*FRONT RH FOGLAMP GARNISH	0.00	0.00	*37.00 F XNN
20	1		*FRONT REINFORCEMENT BAR	0.00	0.00	*320.00 F ?
21	1		*SUPPORT PANEL	0.00	0.00	*56.00 F XR

F=Franchise part.

Sub Total (\$)	5,904.00
+ Margin on L,N Items 10.00% (\$)	590.40
Total Parts (\$)	6,494.40

Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	1,000.00 ⁵⁰⁰
2	1	SPRAY PAINT ON ALL AFFECTED AREA	1,000.00 ⁵⁰⁰
3	1	TO APPLY ANTI RUST TREATMENT	120.00 ⁵⁰
4	1	TO CHECK WIRING SYSTEM	120.00 ³⁰
Sub Total (S\$)			2,240.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	FRONT NUMBER PLATE WITH FRAME	New	45.00 ^{CRA}
2	FRONT BUMPER CLIPS	New	35.00 ^{NEC}
3	FRONT LH & RH FENDER INNER SHIELD CLIPS	New	70.00 ^{XNN}
Gross Labour Cost (S\$)			150.00

Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not Authorise
 - Excess = TBA
 - L/S or P/P repair?
 - Resurvey before paint if P/P repair.
 - Desk Top survey by Simon (6 256 3561)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: